



| | | | |
|------------------------------------|-----------------------------------|-----------------------|------------|
| Brand: | Volkswagen | Mileage(km): | 173826 |
| Model: | Caddy | Number of doors: | 4 |
| Model type: | 2.0 TDI L1H1 BMT Economy | Vehicle length (cm): | |
| License plate: | V524KX | Vehicle width (cm): | |
| Report code: | 9586 | Vehicle height (cm): | |
| Chassis number: | WV1ZZZ2KZX059586 | Vehicle body type: | |
| Type of vehicle: | Commercial | Traction: | Front |
| First int. reg.: | 05/01/2018 | Power(kw): | 55 |
| First NL req.: | 05/01/2018 | Transmission | Manual |
| Color: | <input type="checkbox"/> Metallic | Number of gears | 5 |
| Weight (kg)(kg): | 1473 | Displacement(cc): | 1968 |
| Empty weight(kg): | 1373 | Number of cylinders: | 4 |
| Wheelbase (cm)(cm): | 268 | Fuel type: | Diesel |
| Top speed (km/h): | 152 | Fuel tank capacity: | |
| Cons. in the city (l/100 km): | 5.6 | EU category: | Euro 6 |
| Cons. outside the city (l/100 km): | 4.2 | Energy label: | |
| Average consumption (l/100 km): | 4.7 | NL Tax Rate %: | |
| Acceleration (s): | | CO2 (g/km): | 124 |
| Cargo space (l): | 1473 | Nb. of Axles: | 2 |
| Perm. max weight (kg): | 2127 | APK date: | 05/01/2024 |
| Loading space length (cm): | | Towing Capacity (kg): | |
| Loading space width (cm): | | Load capacity (kg): | 754 |
| Loading space height (cm): | | Trailer Weight (kg): | |
| Hydraulic Installation: | | | |

opties

- | | | |
|----------------------------------------------------------------------|-----------------------------------------------------------------|-------------------------------------------------------------------------|
| <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> Aux connection |
| <input checked="" type="checkbox"/> Central locking system | <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> iPod connection |
| <input checked="" type="checkbox"/> Anti-lock braking system | <input checked="" type="checkbox"/> Halogen headlights | <input checked="" type="checkbox"/> USB connection |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> LED rear lights | <input checked="" type="checkbox"/> Bluetooth car kit |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Airconditioning |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Rear doors | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Towing hook | <input checked="" type="checkbox"/> Cargo area with glass doors | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Fog lamps | <input checked="" type="checkbox"/> Sliding door on the right | |

Tires

| Tire position: | Tire type: | Wheel type: | Tire size: | Tire brand: | Tire profile depth (mm): |
|------------------|------------|-------------|------------|-------------|--------------------------|
| Tire left front | Summer | Steel | 195/65 R15 | Continental | 3 |
| Tire left rear | Summer | Steel | 195/65 R15 | Continental | 3 |
| Tire right front | Summer | Steel | 195/65 R15 | Continental | 2 |
| Tire right rear | Summer | Steel | 195/65 R15 | Continental | 4 |

Additional information

| | | | | |
|-------------------|------|-------------------------------------|----------------------------------------------|----------------------------------------------------------------------|
| No. of keys: | 1 | <input type="checkbox"/> Luxury key | <input type="checkbox"/> Instruction booklet | <input checked="" type="checkbox"/> Airco works |
| Interior color: | Grey | Maintenance booklet: | | <input checked="" type="checkbox"/> Odorless |
| Upholstery: | Stof | | | <input checked="" type="checkbox"/> Clean inside (Interior is clean) |
| No. of seats: | 2 | Stamp date: | | <input checked="" type="checkbox"/> Display ok |
| No. of headrests: | 2 | Last turn mileage(km): | | <input checked="" type="checkbox"/> Vehicle special usage (Taxi) |

Cleaning

- ☒ Clean inside (Interior is clean)
- ☐ Clean outside

🔧 Damages

⊕ Not acceptable



Front bumper - Scratch



Front bumper - Dent



Front left screen - Restyle dent



Left sill - Dent



Rear bumper - Break



Tailgate/ lid - Restyle dent



scheur bestuurdersstoel

🔧 Damages

⊕ Acceptable

⚙️ Extra options







AUTOF[▲]CTOR
SOFTWARE FOR AUTOMOTIVE