



Brand:	Citroen	Mileage(km):	113567
Model:	C4 Cactus	Number of doors:	5
Model type:	1.2 110pk PureTech Business Org.NL	Vehicle length (cm):	
License plate:	SH897Z	Vehicle width (cm):	
Report code:	7248	Vehicle height (cm):	
Chassis number:	VF70PHNZBJE517248	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	13/04/2018	Power(kw):	81
First NL req.:	13/04/2018	Transmission	Manual
Color:	Blue <input checked="" type="checkbox"/> Metallic	Number of gears	5
Weight (kg)(kg):	1105	Displacement(cc):	1199
Empty weight(kg):	1005	Number of cylinders:	3
Wheelbase (cm)(cm):	260	Fuel type:	Petrol
Top speed (km/h):	188	Fuel tank capacity:	
Cons. in the city (l/100 km):	5.5	EU category:	Euro 6
Cons. outside the city (l/100 km):	3.9	Energy label:	C
Average consumption (l/100 km):	4.5	NL Tax Rate %:	
Acceleration (s):	10.3	CO2 (g/km):	104
Cargo space (l):	1105	Nb. of Axles:	2
Perm. max weight (kg):	1565	APK date:	13/04/2026

opties

<input checked="" type="checkbox"/> Alloy wheels	<input checked="" type="checkbox"/> Remote central locking	<input checked="" type="checkbox"/> Cruise control
<input checked="" type="checkbox"/> Digital dashboard	<input checked="" type="checkbox"/> Metallic finish	<input checked="" type="checkbox"/> Airconditioning
<input checked="" type="checkbox"/> Daytime running lights	<input checked="" type="checkbox"/> Halogen headlights	<input checked="" type="checkbox"/> Climate control
<input checked="" type="checkbox"/> Licht Sensor	<input checked="" type="checkbox"/> Rain sensor	<input checked="" type="checkbox"/> Climate control (analog)
<input checked="" type="checkbox"/> bots waarschuwing systeem	<input checked="" type="checkbox"/> Rear wiper	<input checked="" type="checkbox"/> Climate control (digital)
<input checked="" type="checkbox"/> Anti-lock braking system	<input checked="" type="checkbox"/> Rear parking sensors	<input checked="" type="checkbox"/> Large screen navigation
<input checked="" type="checkbox"/> ABS	<input checked="" type="checkbox"/> Rear-seat folding (equal parts)	<input checked="" type="checkbox"/> Electrically operated front windows
<input checked="" type="checkbox"/> Airbag(s)	<input checked="" type="checkbox"/> Rear-seat folding (unequal parts)	<input checked="" type="checkbox"/> Electrically adjustable mirrors
<input checked="" type="checkbox"/> Audio	<input checked="" type="checkbox"/> Luggage cover	<input checked="" type="checkbox"/> Central armrest front
<input checked="" type="checkbox"/> Central locking system	<input checked="" type="checkbox"/> USB connection	<input checked="" type="checkbox"/> Adjustable lumbar support driver's seat
<input checked="" type="checkbox"/> Fog lamps	<input checked="" type="checkbox"/> Bluetooth streaming	<input checked="" type="checkbox"/> Adjustable lumbar support passenger seat
<input checked="" type="checkbox"/> Start/stop system	<input checked="" type="checkbox"/> DAB+	<input checked="" type="checkbox"/> Audio control on the steering wheel
<input checked="" type="checkbox"/> Power steering	<input checked="" type="checkbox"/> Bluetooth car kit	<input checked="" type="checkbox"/> Leather steering wheel
<input checked="" type="checkbox"/> Front seats adjustable in height	<input checked="" type="checkbox"/> Radio	<input checked="" type="checkbox"/> Lane assistance
<input checked="" type="checkbox"/> Multifunctional steering wheel	<input checked="" type="checkbox"/> WiFi	<input checked="" type="checkbox"/> Pedestrian safety system

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	205/55 R16	Vredestein	7
Tire left rear	Summer	Alloy	205/55 R16	Vredestein	5
Tire right front	Summer	Alloy	205/55 R16	Vredestein	7
Tire right rear	Summer	Alloy	205/55 R16	Vredestein	5

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	01/03/2021	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	56498	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- ☒ Clean inside (Interior is clean)
- ☒ Clean outside (Cleaning)

🔧 Damages

⊕ Not acceptable



Front right rim - Scratch



Front bumper - Scratch




Bonnet - Rust formation



Front left screen - Rust formation



Roof - Rust formation





Roof - Rust formation

🔧 Damages

⊕ Acceptable

⚙️ Extra options







AUTOF[▲]CTOR
SOFTWARE FOR AUTOMOTIVE