



Brand:	Mercedes-Benz	Mileage(km):	184079
Model:	C 350	Number of doors:	5
Model type:	350 e Lease Edition   Burmester	Vehicle length (cm):	
License plate:	GK518R	Vehicle width (cm):	
Report code:	5723	Vehicle height (cm):	
Chassis number:	WDD2052471F205723	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Rear
First int. reg.:	19/06/2015	Power(kw):	155
First NL req.:	19/06/2015	Transmission	Automatic
Color:	Beige <input checked="" type="checkbox"/> Metallic	Number of gears	7
Weight (kg)(kg):	1840	Displacement(cc):	1991
Empty weight(kg):	1740	Number of cylinders:	4
Wheelbase (cm)(cm):	284	Fuel type:	Hybride (Electro/Benzine) plug-in
Top speed (km/h):	246	Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	Euro 6
Cons. outside the city (l/100 km):		Energy label:	A
Avarage consumption (l/100 km):		NL Tax Rate %:	25
Acceleration (s):	6.2	CO2 (g/km):	49
Cargo space (l):	1840	Nb. of Axles:	2
Perm. max weight (kg):	2305	APK date:	19/06/2025

## opties

<input checked="" type="checkbox"/> Alloy wheels	<input checked="" type="checkbox"/> Rain sensor	<input checked="" type="checkbox"/> Climate control (digital)
<input checked="" type="checkbox"/> Air suspension	<input checked="" type="checkbox"/> Rear wiper	<input checked="" type="checkbox"/> Climate control (L/R separated)
<input checked="" type="checkbox"/> Daytime running lights	<input checked="" type="checkbox"/> Rear view camera	<input checked="" type="checkbox"/> Large screen navigation
<input checked="" type="checkbox"/> Licht Sensor	<input checked="" type="checkbox"/> Rear parking sensors	<input checked="" type="checkbox"/> Keyless start/stop
<input checked="" type="checkbox"/> Towing hook	<input checked="" type="checkbox"/> Front parking sensors	<input checked="" type="checkbox"/> Electrically operated rear windows
<input checked="" type="checkbox"/> Anti-lock braking system	<input checked="" type="checkbox"/> Rear-seat folding (equal parts)	<input checked="" type="checkbox"/> Electrically operated front windows
<input checked="" type="checkbox"/> ABS	<input checked="" type="checkbox"/> Rear-seat folding (unequal parts)	<input checked="" type="checkbox"/> Electrically folding mirrors
<input checked="" type="checkbox"/> Airbag(s)	<input checked="" type="checkbox"/> Luggage cover	<input checked="" type="checkbox"/> Electrically adjustable mirrors
<input checked="" type="checkbox"/> Audio	<input checked="" type="checkbox"/> Trunk opens electrically	<input checked="" type="checkbox"/> Electrically adjustable driver's seat
<input checked="" type="checkbox"/> Burmeister	<input checked="" type="checkbox"/> Charging cable 220V	<input checked="" type="checkbox"/> Electrically adjustable passenger seat
<input checked="" type="checkbox"/> Central locking system	<input checked="" type="checkbox"/> USB connection	<input checked="" type="checkbox"/> Electrically heated driver's seat
<input checked="" type="checkbox"/> Start/stop system	<input checked="" type="checkbox"/> Bluetooth streaming	<input checked="" type="checkbox"/> Electrically heated passenger seat
<input checked="" type="checkbox"/> Power steering	<input checked="" type="checkbox"/> CD changer	<input checked="" type="checkbox"/> Central armrest front
<input checked="" type="checkbox"/> Front seats adjustable in height	<input checked="" type="checkbox"/> Radio/CD player	<input checked="" type="checkbox"/> Extendable passenger seat
<input checked="" type="checkbox"/> Multifunctional steering wheel	<input checked="" type="checkbox"/> Bluetooth car kit	<input checked="" type="checkbox"/> Extendable driver's seat
<input checked="" type="checkbox"/> Remote central locking	<input checked="" type="checkbox"/> Radio	<input checked="" type="checkbox"/> Adjustable lumbar support driver's seat
<input checked="" type="checkbox"/> Roof rail (silver)	<input checked="" type="checkbox"/> WiFi	<input checked="" type="checkbox"/> Adjustable lumbar support passenger seat
<input checked="" type="checkbox"/> Metallic finish	<input checked="" type="checkbox"/> Cruise control	<input checked="" type="checkbox"/> Audio control on the steering wheel
<input checked="" type="checkbox"/> LED headlights	<input checked="" type="checkbox"/> Black top interior	<input checked="" type="checkbox"/> Leather steering wheel
<input checked="" type="checkbox"/> LED rear lights	<input checked="" type="checkbox"/> Airconditioning	<input checked="" type="checkbox"/> Switch flippers
<input checked="" type="checkbox"/> Exterior mirrors in car body color	<input checked="" type="checkbox"/> Airconditioning in the back	<input checked="" type="checkbox"/> Pedestrian safety system
<input checked="" type="checkbox"/> Exterior mirrors with step light	<input checked="" type="checkbox"/> Climate control	<input checked="" type="checkbox"/> Dead angle assistance
<input checked="" type="checkbox"/> Privacy glass	<input checked="" type="checkbox"/> Climate control (analog)	

## Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	All weather	Alloy	245/40 R18	Michelin	6
Tire left rear	All weather	Alloy	245/40 R18	Michelin	5
Tire right front	All weather	Alloy	245/40 R18	Michelin	6
Tire right rear	All weather	Alloy	245/40 R18	Michelin	5

## Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Half stof/leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	14/06/2024	<input checked="" type="checkbox"/> Display ok

No. of headrests:

5

Last turn mileage(km):

180833

☒ Vehicle special usage (None)

## Cleaning

☒ Clean inside (Interior is clean)

☒ Clean outside (Polishing)

## Damages

 Not acceptable



Front left screen - Dent



Front right rim - Scratch



Bonnet - Paint repair



Front left screen - Paint repair



Rear left rim - Scratch



Rear bumper - Scratch



Rear right rim - Scratch



Rear right screen - Restyle dent





Bestuurderstoel beschadigd



## Damages

 Acceptable

## Extra options









AUTOF<sup>▲</sup>CTOR  
SOFTWARE FOR AUTOMOTIVE