



| | | | |
|------------------------------------|---|----------------------|-----------|
| Brand: | Volvo | Mileage(km): | 133759 |
| Model: | XC40 | Number of doors: | |
| Model type: | 1.5 T3 Inscription Leder Stoelverwarming | Vehicle length (cm): | |
| License plate: | 231710 | Vehicle width (cm): | |
| Report code: | 1710 | Vehicle height (cm): | |
| Chassis number: | YV1XZ15VDL2231710 | Vehicle body type: | |
| Type of vehicle: | Luxury | Traction: | |
| First int. reg.: | 02/10/2019 | Power(kw): | 120 |
| First NL req.: | 02/10/2019 | Transmission | Automatic |
| Color: | <input checked="" type="checkbox"/> Metallic | Number of gears | |
| Weight (kg)(kg): | | Displacement(cc): | 1477 |
| Empty weight(kg): | | Number of cylinders: | |
| Wheelbase (cm)(cm): | | Fuel type: | Petrol |
| Top speed (km/h): | | Fuel tank capacity: | |
| Cons. in the city (l/100 km): | | EU category: | |
| Cons. outside the city (l/100 km): | | Energy label: | |
| Avarage consumption (l/100 km): | | NL Tax Rate %: | |
| Acceleration (s): | | CO2 (g/km): | |
| Cargo space (l): | | Nb. of Axles: | 2 |
| Perm. max weight (kg): | | APK date: | |

opties

| | | |
|--|---|--|
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Privacy glass | <input checked="" type="checkbox"/> Climate control (analog) |
| <input checked="" type="checkbox"/> Leather upholstery | <input checked="" type="checkbox"/> Rain sensor | <input checked="" type="checkbox"/> Climate control (digital) |
| <input checked="" type="checkbox"/> Digital dashboard | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Large screen navigation |
| <input checked="" type="checkbox"/> Daytime running lights | <input checked="" type="checkbox"/> 360 ° camera system | <input checked="" type="checkbox"/> Keyless start/stop |
| <input checked="" type="checkbox"/> Licht Sensor | <input checked="" type="checkbox"/> Rear view camera | <input checked="" type="checkbox"/> Electrically operated rear windows |
| <input checked="" type="checkbox"/> bots waarschuwing systeem | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Anti-lock braking system | <input checked="" type="checkbox"/> Front parking sensors | <input checked="" type="checkbox"/> Electrically heated windscreen |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> Rear-seat folding (equal parts) | <input checked="" type="checkbox"/> Electrically folding mirrors |
| <input checked="" type="checkbox"/> Central locking system | <input checked="" type="checkbox"/> Rear-seat folding (unequal parts) | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Start/stop system | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Central armrest front |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> Trunk opens electrically | <input checked="" type="checkbox"/> Adjustable lumbar support driver's seat |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> USB connection | <input checked="" type="checkbox"/> Adjustable lumbar support passenger seat |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> Bluetooth streaming | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> DAB+ | <input checked="" type="checkbox"/> Leather steering wheel |
| <input checked="" type="checkbox"/> Roof rail (silver) | <input checked="" type="checkbox"/> Bluetooth car kit | <input checked="" type="checkbox"/> Lane assistance |
| <input checked="" type="checkbox"/> Metallic finish | <input checked="" type="checkbox"/> Radio | <input checked="" type="checkbox"/> Pedestrian safety system |
| <input checked="" type="checkbox"/> LED headlights | <input checked="" type="checkbox"/> Cruise control | <input checked="" type="checkbox"/> Dead angle assistance |
| <input checked="" type="checkbox"/> LED rear lights | <input checked="" type="checkbox"/> Airconditioning | |
| <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Climate control | |

Tires

| Tire position: | Tire type: | Wheel type: | Tire size: | Tire brand: | Tire profile depth (mm): |
|------------------|------------|-------------|------------|-------------|--------------------------|
| Tire left front | Summer | Alloy | 235/55 R18 | Michelin | 5 |
| Tire left rear | Summer | Alloy | 235/55 R18 | Michelin | 6 |
| Tire right front | Summer | Alloy | 235/55 R18 | Michelin | 5 |
| Tire right rear | Summer | Alloy | 235/55 R18 | Michelin | 6 |

Additional information

| | | | | |
|-------------------|-------|-------------------------------------|--|--|
| No. of keys: | 2 | <input type="checkbox"/> Luxury key | <input type="checkbox"/> Instruction booklet | <input checked="" type="checkbox"/> Airco works |
| Interior color: | Black | Maintenance booklet: | (serviceboekje (papier)) | <input checked="" type="checkbox"/> Odorless |
| Upholstery: | Leder | | | <input checked="" type="checkbox"/> Clean inside (Interior is clean) |
| No. of seats: | 5 | Stamp date: | 05/09/2024 | <input checked="" type="checkbox"/> Display ok |
| No. of headrests: | 5 | Last turn mileage(km): | 123487 | <input checked="" type="checkbox"/> Vehicle special usage (Taxi) |

Cleaning

☒ Clean inside (Interior is clean)

☒ Clean outside (Cleaning)

Damages

 Not acceptable



Front bumper - Scratch



Front left rim - Scratch



Rear left rim - Scratch



Roof - Scratch

Damages

 Acceptable

Extra options





