



|                                    |   |                      |            |
|------------------------------------|---|----------------------|------------|
| Brand:                             | Opel  | Mileage(km):         | 84661      |
| Model:                             | Insignia  | Number of doors:     | 5          |
| Model type:                        | 1.5 CDTI Business Elegance PANORAMA               | Vehicle length (cm): |            |
| License plate:                     | L125BB  | Vehicle width (cm):  |            |
| Report code:                       | 5301  | Vehicle height (cm): |            |
| Chassis number:                    | W0VZT8EN0M1015301                                 | Vehicle body type:   |            |
| Type of vehicle:                   | Luxury  | Traction:            | Front      |
| First int. reg.:                   | 14/04/2021  | Power(kw):           | 90         |
| First NL req.:                     | 14/04/2021  | Transmission         | Manual     |
| Color:                             | Blue <input checked="" type="checkbox"/> Metallic | Number of gears      | 6          |
| Weight (kg)(kg):                   | 1585  | Displacement(cc):    | 1496       |
| Empty weight(kg):                  | 1485  | Number of cylinders: | 3          |
| Wheelbase (cm)(cm):                | 283   | Fuel type:           | Diesel     |
| Top speed (km/h):                  | 202   | Fuel tank capacity:  |            |
| Cons. in the city (l/100 km):      | 4.7   | EU category:         | Euro 6     |
| Cons. outside the city (l/100 km): | 3.5   | Energy label:        | B          |
| Average consumption (l/100 km):    | 3.9   | NL Tax Rate %:       |            |
| Acceleration (s):                  | 11.6  | CO2 (g/km):          | 104        |
| Cargo space (l):                   | 1585  | Nb. of Axles:        | 2          |
| Perm. max weight (kg):             | 2175  | APK date:            | 13/11/2025 |

## opties

|  |   |  |
|--|---|--|
| <input checked="" type="checkbox"/> Alloy wheels                     | <input checked="" type="checkbox"/> LED headlights              | <input checked="" type="checkbox"/> Climate control (digital)                |
| <input checked="" type="checkbox"/> Daytime running lights           | <input checked="" type="checkbox"/> LED rear lights             | <input checked="" type="checkbox"/> Climate control (L/R separated)          |
| <input checked="" type="checkbox"/> Licht Sensor                     | <input checked="" type="checkbox"/> Rain sensor                 | <input checked="" type="checkbox"/> Large screen navigation                  |
| <input checked="" type="checkbox"/> bots waarschuwing systeem        | <input checked="" type="checkbox"/> Rear wiper                  | <input checked="" type="checkbox"/> Keyless entry                            |
| <input checked="" type="checkbox"/> Anti-lock braking system         | <input checked="" type="checkbox"/> Rear view camera            | <input checked="" type="checkbox"/> Keyless entry/start/stop                 |
| <input checked="" type="checkbox"/> ABS                              | <input checked="" type="checkbox"/> Rear parking sensors        | <input checked="" type="checkbox"/> Electrically operated rear windows       |
| <input checked="" type="checkbox"/> Airbag(s)                        | <input checked="" type="checkbox"/> Front parking sensors       | <input checked="" type="checkbox"/> Electrically operated front windows      |
| <input checked="" type="checkbox"/> Audio                            | <input checked="" type="checkbox"/> Luggage cover               | <input checked="" type="checkbox"/> Electrically folding mirrors             |
| <input checked="" type="checkbox"/> bots herkenning systeem          | <input checked="" type="checkbox"/> Trunk opens electrically    | <input checked="" type="checkbox"/> Electrically adjustable mirrors          |
| <input checked="" type="checkbox"/> Central locking system           | <input checked="" type="checkbox"/> USB connection              | <input checked="" type="checkbox"/> Central armrest front                    |
| <input checked="" type="checkbox"/> Fog lamps                        | <input checked="" type="checkbox"/> DAB+                        | <input checked="" type="checkbox"/> Extendable passenger seat                |
| <input checked="" type="checkbox"/> Start/stop system                | <input checked="" type="checkbox"/> Bluetooth car kit           | <input checked="" type="checkbox"/> Extendable driver's seat                 |
| <input checked="" type="checkbox"/> Power steering                   | <input checked="" type="checkbox"/> Cruise control (adaptive)   | <input checked="" type="checkbox"/> Adjustable lumbar support driver's seat  |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> Cruise control              | <input checked="" type="checkbox"/> Adjustable lumbar support passenger seat |
| <input checked="" type="checkbox"/> Multifunctional steering wheel   | <input checked="" type="checkbox"/> Head-up Display             | <input checked="" type="checkbox"/> Audio control on the steering wheel      |
| <input checked="" type="checkbox"/> Remote central locking           | <input checked="" type="checkbox"/> Black top interior          | <input checked="" type="checkbox"/> Leather steering wheel                   |
| <input checked="" type="checkbox"/> Roof rail (silver)               | <input checked="" type="checkbox"/> Airconditioning             | <input checked="" type="checkbox"/> Lane assistance                          |
| <input checked="" type="checkbox"/> Metallic finish                  | <input checked="" type="checkbox"/> Airconditioning in the back | <input checked="" type="checkbox"/> Pedestrian safety system                 |
| <input checked="" type="checkbox"/> Panoramic roof (electrical)      | <input checked="" type="checkbox"/> Climate control             | <input checked="" type="checkbox"/> Dead angle assistance                    |

## Tires

| Tire position:   | Tire type: | Wheel type: | Tire size: | Tire brand: | Tire profile depth (mm): |
|------------------|------------|-------------|------------|-------------|--------------------------|
| Tire left front  | Summer     | Alloy       | 245/45 R18 | Viking      | 6                        |
| Tire left rear   | Summer     | Alloy       | 245/45 R18 | Viking      | 6                        |
| Tire right front | Summer     | Alloy       | 245/45 R18 | Viking      | 6                        |
| Tire right rear  | Summer     | Alloy       | 245/45 R18 | Bridgestone | 6                        |

## Additional information

|                   |                 |                                     |  |  |
|-------------------|-----------------|-------------------------------------|--|--|
| No. of keys:      | 2               | <input type="checkbox"/> Luxury key | <input type="checkbox"/> Instruction booklet | <input checked="" type="checkbox"/> Airco works                      |
| Interior color:   | Black           | Maintenance booklet:                | (serviceboekje (papier))                     | <input checked="" type="checkbox"/> Odorless                         |
| Upholstery:       | Half stof/leder |                                     |  | <input checked="" type="checkbox"/> Clean inside (Interior is clean) |
| No. of seats:     | 5               | Stamp date:                         | 07/08/2024                                   | <input checked="" type="checkbox"/> Display ok                       |
| No. of headrests: | 5               | Last turn mileage(km):              | 78662  | <input checked="" type="checkbox"/> Vehicle special usage (None)     |

## ⚠ Cleaning

☒ Clean inside (Interior is clean)

☐ Clean outside

## 🔧 Damages

⊕ Not acceptable



Left sill - Dent



Rear right screen - Paint repair



Rear right door - Paint repair



Front left door - Paint repair

## 🔧 Damages

⊕ Acceptable

## ⚙ Extra options







