



Brand:	Opel	Mileage(km):	149692
Model:	Astra Sports Tourer	Number of doors:	5
Model type:	1.2 Business Edition	Vehicle length (cm):	
License plate:	K082KT	Vehicle width (cm):	
Report code:	6047	Vehicle height (cm):	
Chassis number:	W0VBD8ES6M8006047	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	12/01/2021	Power(kw):	96
First NL reg.:	12/01/2021	Transmission:	Manual
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears:	6
Weight (kg)(ka):	1355	Displacement(cc):	1199
Empty weight(ka):	1255	Number of cylinders:	3
Wheelbase (cm)(cm):	266	Fuel type:	Petrol
Top speed (km/h):	215	Fuel tank capacity:	
Cons. in the city (l/100 km):	5.4	EU category:	Euro 6
Cons. outside the city (l/100 km):	3.9	Energy label:	A
Average consumption (l/100 km):	4.4	NL Tax Rate %:	
Acceleration (s):	10.1	CO2 (g/km):	102
Cargo space (l):	1355	Nb. of Axles:	2
Perm. max weight (kg):	1870	APK date:	12/01/2027

opties

- | | | |
|--|--|---|
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> USB connection |
| <input checked="" type="checkbox"/> Daytime running lights | <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> DAB+ |
| <input checked="" type="checkbox"/> Licht Sensor | <input checked="" type="checkbox"/> Roof rail (silver) | <input checked="" type="checkbox"/> Bluetooth car kit |
| <input checked="" type="checkbox"/> Anti-lock braking system | <input checked="" type="checkbox"/> Metallic finish | <input checked="" type="checkbox"/> Cruise control |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> LED headlights | <input checked="" type="checkbox"/> Airconditioning |
| <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> LED rear lights | <input checked="" type="checkbox"/> Large screen navigation |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Electrically operated rear windows |
| <input checked="" type="checkbox"/> Central locking system | <input checked="" type="checkbox"/> Rain sensor | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Fog lamps | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> Luggage cover | |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	205/55 R16	Continental	6
Tire left rear	Summer	Alloy	205/55 R16	Continental	6
Tire right front	Summer	Alloy	205/55 R16	Continental	6
Tire right rear	Summer	Alloy	205/55 R16	Continental	6

Additional information

No. of keys:	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof		<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- Clean inside (Interior is clean)
- Clean outside (Polishing)

Damages

Not acceptable



Front bumper - Scratch




Bonnet - Stone chippings



Windscreen - Pip



Rear left door - Restyle dent



Rear left screen - Restyle dent



Rear bumper - Paint repair



Right C- column - Restyle dent



Rear right screen - Restyle dent

 Damages

 Acceptable

 Extra options



