



Dacia	Mileage(km):	161396
Duster	Number of doors:	5
1.0 TCe Bi-Fuel Prestige	Vehicle length (cm):	
L848KK	Vehicle width (cm):	
6086	Vehicle height (cm):	
VF1HJD20867386086	Vehicle body type:	
Luxury	Traction:	Front
12/06/2021	Power(kw):	74
12/06/2021	Transmission	Manual
White Metallic	Number of gears	5
1367	Displacement(cc):	999
1267	Number of cylinders:	4

Fuel type:

EU category:

Energy label:

NL Tax Rate %:

CO2 (g/km):

Nb. of Axles:

APK date:

Fuel tank capacity:

Inspected by: Maurice Otten

Petrol

Euro 6

в

115

12/06/2025

2

### 📽 opties

Alloy wheels Daytime running lights Licht Sensor Towing hook Anti-lock braking system ABS Airbag(s) Audio Central locking system Fog lamps Start/stop system Power steering Front seats adjustable in height Multifunctional steering wheel Remote central locking Roof rail (silver) Halogen headlights Privacy glass

$\checkmark$	Rear wiper
~	360 ° camera system
2222222222222	Rear view camera
$\overline{}$	Rear parking sensors
$\overline{}$	Towbar with fixed ball
$\overline{}$	Rear-seat folding (equal parts)
$\overline{}$	Rear-seat folding (unequal parts)
	Luggage cover
$\overline{}$	Aux connection
$\overline{}$	iPod connection
$\overline{}$	USB connection
$\checkmark$	Bluetooth streaming
	DAB+
	Radio/CD/MP3 player
$\overline{}$	Bluetooth car kit
$\mathbf{v}$	Radio
~	Cruise control
~	Airconditioning

267

168

8.6

6.6

7.3

13.8

1367

1771

Brand: Model: Model type: License plate: Report code: Chassis number: Type of vehicle: First int. reg.: Color: Color: Weight (kg)(kg): Empty weight(kg):

Top speed (km/h):

Acceleration (s):

Cargo space (I):

Perm. max weight (kg):

Cons. in the city (I/100 km):

Cons. outside the city (l/100 km):

Avarage consumption (I/100 km):

#### Climate control 2222222222 Climate control (analog) Climate control (digital) Large screen navigation Keyless entry Keyless entry/start/stop Keyless start/stop Electrically operated rear windows Electrically operated front windows ~ Electrically adjustable mirrors Central armrest front 222222 Adjustable lumbar support driver's seat Adjustable lumbar support passenger seat Audio control on the steering wheel Leather steering wheel Dead angle assistance

¢\$ Tires					
Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	All weather	Alloy	215/60 R17	delinte	6
Tire left rear	All weather	Alloy	215/60 R17	rotalla	6
Tire right front	All weather	Alloy	215/60 R17	delinte	6
Tire right rear	All weather	Alloy	215/60 R17	rotalla	6

A	Additional information				
	No. of keys:	2 Luxury key	Instruction booklet		Airco works
	Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	Odorless
	Upholstery:	Stof			Clean inside (Interior is clean)
	No. of seats:	5	Stamp date:	18/10/2024	Display ok
	No. of headrests:	5	Last turn mileage(km):	140680	Vehicle special usage (None)


#### Cleaning

Clean inside (Interior is clean)

### Clean outside (Cleaning)

### ۶ Damages

# Not acceptable



Front bumper - Paint repair



Rear bumper - Scratch




Front left door - Restyle dent



Damages
Acceptable

Comparison






























































## AUTOFACTOR SOFTWARE FOR AUTOMOTIVE