



<b>Brand:</b>	Peugeot	<b>Mileage(km):</b>	157489
<b>Model:</b>	308	<b>Number of doors:</b>	5
<b>Model type:</b>	1.6 e-THP GT 205   Navi   Clima   Cruise   Camera   PDC   Denon Audio	<b>Vehicle length (cm):</b>	
<b>License plate:</b>	ZF286N	<b>Vehicle width (cm):</b>	
<b>Report code:</b>	2472	<b>Vehicle height (cm):</b>	
<b>Chassis number:</b>	VF3L35GTHHS062472	<b>Vehicle body type:</b>	
<b>Type of vehicle:</b>	Luxury	<b>Traction:</b>	Front
<b>First int. reg.:</b>	09/03/2017	<b>Power(kw):</b>	151
<b>First NL reg.:</b>	07/05/2019	<b>Transmission</b>	Manual
<b>Color:</b>	Grey <input type="checkbox"/> Metallic	<b>Number of gears</b>	
<b>Weight (kg)(kg):</b>	1275	<b>Displacement(cc):</b>	1598
<b>Empty weight(kg):</b>	1175	<b>Number of cylinders:</b>	4
<b>Wheelbase (cm)(cm):</b>	262	<b>Fuel type:</b>	Petrol
<b>Top speed (km/h):</b>	235	<b>Fuel tank capacity:</b>	
<b>Cons. in the city (l/100 km):</b>	7.4	<b>EU category:</b>	Euro 6
<b>Cons. outside the city (l/100 km):</b>	4.6	<b>Energy label:</b>	C
<b>Average consumption (l/100 km):</b>	5.6	<b>NL Tax Rate %:</b>	
<b>Acceleration (s):</b>	7.5	<b>CO2 (g/km):</b>	130
<b>Cargo space (l):</b>	1275	<b>Nb. of Axles:</b>	2
<b>Perm. max weight (kg):</b>	1790	<b>APK date:</b>	09/03/2026

## opties

<input checked="" type="checkbox"/> Alloy wheels	<input checked="" type="checkbox"/> Privacy glass	<input checked="" type="checkbox"/> Airconditioning
<input checked="" type="checkbox"/> Leather upholstery	<input checked="" type="checkbox"/> Rain sensor	<input checked="" type="checkbox"/> Climate control
<input checked="" type="checkbox"/> Daytime running lights	<input checked="" type="checkbox"/> Rear wiper	<input checked="" type="checkbox"/> Climate control (digital)
<input checked="" type="checkbox"/> Licht Sensor	<input checked="" type="checkbox"/> Rear view camera	<input checked="" type="checkbox"/> Climate control (L/R separated)
<input checked="" type="checkbox"/> Anti-lock braking system	<input checked="" type="checkbox"/> Rear parking sensors	<input checked="" type="checkbox"/> Large screen navigation
<input checked="" type="checkbox"/> ABS	<input checked="" type="checkbox"/> Front parking sensors	<input checked="" type="checkbox"/> Keyless entry
<input checked="" type="checkbox"/> Airbag(s)	<input checked="" type="checkbox"/> Luggage cover	<input checked="" type="checkbox"/> Keyless entry/start/stop
<input checked="" type="checkbox"/> Audio	<input checked="" type="checkbox"/> Aux connection	<input checked="" type="checkbox"/> Keyless start/stop
<input checked="" type="checkbox"/> Central locking system	<input checked="" type="checkbox"/> iPod connection	<input checked="" type="checkbox"/> Electrically operated rear windows
<input checked="" type="checkbox"/> Fog lamps	<input checked="" type="checkbox"/> USB connection	<input checked="" type="checkbox"/> Electrically operated front windows
<input checked="" type="checkbox"/> Start/stop system	<input checked="" type="checkbox"/> CD changer	<input checked="" type="checkbox"/> Electrically folding mirrors
<input checked="" type="checkbox"/> Power steering	<input checked="" type="checkbox"/> Radio/CD player	<input checked="" type="checkbox"/> Electrically adjustable mirrors
<input checked="" type="checkbox"/> Front seats adjustable in height	<input checked="" type="checkbox"/> Radio/CD/MP3 player	<input checked="" type="checkbox"/> Central armrest front
<input checked="" type="checkbox"/> Multifunctional steering wheel	<input checked="" type="checkbox"/> Bluetooth car kit	<input checked="" type="checkbox"/> Sport seats
<input checked="" type="checkbox"/> Remote central locking	<input checked="" type="checkbox"/> WiFi	<input checked="" type="checkbox"/> Adjustable lumbar support driver's seat
<input checked="" type="checkbox"/> Sports package (exterior)	<input checked="" type="checkbox"/> Cruise control	<input checked="" type="checkbox"/> Adjustable lumbar support passenger seat
<input checked="" type="checkbox"/> LED headlights	<input checked="" type="checkbox"/> Sports package (interior)	<input checked="" type="checkbox"/> Audio control on the steering wheel
<input checked="" type="checkbox"/> Exterior mirrors in car body color	<input checked="" type="checkbox"/> Black top interior	<input checked="" type="checkbox"/> Leather steering wheel

## Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	225/40 R18	Continental	5
Tire left rear	Summer	Alloy	225/40 R18	Continental	5
Tire right front	Summer	Alloy	225/40 R18	Continental	5
Tire right rear	Summer	Alloy	225/40 R18	Continental	5

## Additional information

<b>No. of keys:</b>	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
<b>Interior color:</b>	Black	<b>Maintenance booklet:</b>	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
<b>Upholstery:</b>	Leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
<b>No. of seats:</b>	5	<b>Stamp date:</b>	25/01/2021	<input checked="" type="checkbox"/> Display ok
<b>No. of headrests:</b>	5	<b>Last turn mileage(km):</b>	54177	<input checked="" type="checkbox"/> Vehicle special usage (None)

## Cleaning

☒ Clean inside (Interior is clean)

☐ Clean outside

## Damages

⊕ Not acceptable



Front left rim - Scratch



Rear left rim - Scratch



Rear right rim - Scratch



Front right rim - Scratch



Front bumper - Stone chippings




Front bumper - Stone chippings



Bonnet - Stone chippings



Front left screen - Scratch



Rear left screen - Dent



Rear bumper - Break



Rear right screen - Rust formation



Rear right door - Rust formation



Front left door - Scratch



Front left screen - Paint repair



Brandgaten bestuurdersstoel

🔑 Damages

⊕ Acceptable

⚙️ Extra options







