



Brand:	Peugeot	Mileage(km):	136942
Model:	2008	Number of doors:	5
Model type:	1.2 PureTech Blue Lease Active	Vehicle length (cm):	
License plate:	K813KD	Vehicle width (cm):	
Report code:	0861	Vehicle height (cm):	
Chassis number:	VR3USHNKKLJ870861	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	02/02/2021	Power(kw):	75
First NL req.:	02/02/2021	Transmission	Manual
Color:	White <input type="checkbox"/> Metallic	Number of gears	6
Weight (kg)(kg):	1263	Displacement(cc):	1199
Empty weight(kg):	1163	Number of cylinders:	3
Wheelbase (cm)(cm):	261	Fuel type:	Petrol
Top speed (km/h):	183	Fuel tank capacity:	
Cons. in the city (l/100 km):	5.5	EU category:	Euro 6
Cons. outside the city (l/100 km):	4	Energy label:	B
Avarage consumption (l/100 km):	4.6	NL Tax Rate %:	
Acceleration (s):	12	CO2 (g/km):	105
Cargo space (l):	1263	Nb. of Axles:	2
Perm. max weight (kg):	1710	APK date:	28/02/2027

opties

<input checked="" type="checkbox"/> Daytime running lights	<input checked="" type="checkbox"/> LED rear lights	<input checked="" type="checkbox"/> Cruise control
<input checked="" type="checkbox"/> Licht Sensor	<input checked="" type="checkbox"/> Exterior mirrors in car body color	<input checked="" type="checkbox"/> Airconditioning
<input checked="" type="checkbox"/> Towing hook	<input checked="" type="checkbox"/> Rain sensor	<input checked="" type="checkbox"/> Climate control
<input checked="" type="checkbox"/> bots waarschuwing systeem	<input checked="" type="checkbox"/> Rear wiper	<input checked="" type="checkbox"/> Climate control (analog)
<input checked="" type="checkbox"/> Anti-lock braking system	<input checked="" type="checkbox"/> Rear parking sensors	<input checked="" type="checkbox"/> Climate control (digital)
<input checked="" type="checkbox"/> ABS	<input checked="" type="checkbox"/> Towbar with detachable ball	<input checked="" type="checkbox"/> Large screen navigation
<input checked="" type="checkbox"/> Airbag(s)	<input checked="" type="checkbox"/> Rear-seat folding (equal parts)	<input checked="" type="checkbox"/> Electrically operated rear windows
<input checked="" type="checkbox"/> Audio	<input checked="" type="checkbox"/> Rear-seat folding (unequal parts)	<input checked="" type="checkbox"/> Electrically operated front windows
<input checked="" type="checkbox"/> Central locking system	<input checked="" type="checkbox"/> Luggage cover	<input checked="" type="checkbox"/> Electrically folding mirrors
<input checked="" type="checkbox"/> Fog lamps	<input checked="" type="checkbox"/> iPod connection	<input checked="" type="checkbox"/> Electrically adjustable mirrors
<input checked="" type="checkbox"/> Start/stop system	<input checked="" type="checkbox"/> USB connection	<input checked="" type="checkbox"/> Audio control on the steering wheel
<input checked="" type="checkbox"/> Power steering	<input checked="" type="checkbox"/> Bluetooth streaming	<input checked="" type="checkbox"/> Leather steering wheel
<input checked="" type="checkbox"/> Front seats adjustable in height	<input checked="" type="checkbox"/> DAB+	<input checked="" type="checkbox"/> Lane assistance
<input checked="" type="checkbox"/> Multifunctional steering wheel	<input checked="" type="checkbox"/> Bluetooth car kit	<input checked="" type="checkbox"/> Pedestrian safety system
<input checked="" type="checkbox"/> Remote central locking	<input checked="" type="checkbox"/> Radio	
<input checked="" type="checkbox"/> LED headlights	<input checked="" type="checkbox"/> WiFi	

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Winter	Steel	215/65 R16	Goodyear	8
Tire left rear	Winter	Steel	215/65 R16	Goodyear	5
Tire right front	Winter	Steel	215/65 R16	Goodyear	5
Tire right rear	Winter	Steel	215/65 R16	Goodyear	8

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	02/09/2024	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	131431	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- ☒ Clean inside (Interior is clean)

☒ Clean outside (Polishing)

Damages

⊕ Not acceptable



Rear bumper - Scratch



Front left door - Restyle dent



Left B- column - Dent



Right B- column - Restyle dent



Deur LV beschadigd



Damages

⊕ Acceptable

Extra options







AUTOF[▲]CTOR
SOFTWARE FOR AUTOMOTIVE