



Brand:	Citroen	Mileage(km):	131114
Model:	C4 Cactus	Number of doors:	5
Model type:	1.2 PureTech Origins	Vehicle length (cm):	
License plate:	G703XG	Vehicle width (cm):	
Report code:	9548	Vehicle height (cm):	
Chassis number:	VF70PHNPMKE549548	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	04/02/2020	Power(kw):	81
First NL reg.:	04/02/2020	Transmission	Manual
Color:	Grey <input checked="" type="checkbox"/> Metallic	Number of gears	6
Weight (kg)(kg):	1160	Displacement(cc):	1199
Empty weight(kg):	1060	Number of cylinders:	3
Wheelbase (cm)(cm):	260	Fuel type:	Petrol
Top speed (km/h):	197	Fuel tank capacity:	
Cons. in the city (l/100 km):	5.7	EU category:	Euro 6
Cons. outside the city (l/100 km):	4	Energy label:	C
Average consumption (l/100 km):	4.6	NL Tax Rate %:	
Acceleration (s):	10.4	CO2 (g/km):	106
Cargo space (l):	1160	Nb. of Axles:	2
Perm. max weight (kg):	1585	APK date:	04/02/2026

opties

- | | | |
|--|--|--|
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> Cruise control |
| <input checked="" type="checkbox"/> Digital dashboard | <input checked="" type="checkbox"/> Metallic finish | <input checked="" type="checkbox"/> Airconditioning |
| <input checked="" type="checkbox"/> Daytime running lights | <input checked="" type="checkbox"/> LED rear lights | <input checked="" type="checkbox"/> Climate control |
| <input checked="" type="checkbox"/> Licht Sensor | <input checked="" type="checkbox"/> Rain sensor | <input checked="" type="checkbox"/> Climate control (digital) |
| <input checked="" type="checkbox"/> Anti-lock braking system | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Large screen navigation |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Removable rear windows | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> Rear view camera | <input checked="" type="checkbox"/> Electrically folding mirrors |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Central locking system | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Central armrest front |
| <input checked="" type="checkbox"/> Fog lamps | <input checked="" type="checkbox"/> USB connection | <input checked="" type="checkbox"/> Adjustable lumbar support driver's seat |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> DAB+ | <input checked="" type="checkbox"/> Adjustable lumbar support passenger seat |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> Bluetooth car kit | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> Radio | <input checked="" type="checkbox"/> Leather steering wheel |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	All weather	Alloy	205/50 R17	Continental	5
Tire left rear	All weather	Alloy	205/50 R17	Continental	6
Tire right front	All weather	Alloy	205/50 R17	Continental	5
Tire right rear	All weather	Alloy	205/50 R17	Continental	6

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	07/04/2023	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	77296	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- ☒ Clean inside (Interior is clean)
- ☐ Clean outside

Damages


⊗ Not acceptable



Front left rim - Scratch



Front right rim - Scratch



Left A- column - Scratch




Front left door - Scratch



Roof - Restyle dent



Tailgate/ lid - Scratch






Front left door - Restyle dent


Damages

⊗ Acceptable

Extra options







AUTOF[▲]CTOR
SOFTWARE FOR AUTOMOTIVE