

#### Inspected by: Rob Datema



Brand:		B.C (1)	444740
Brand:	Ford	Mileage(km):	141713
Model:	Fiesta	Number of doors:	5
Model type:	1.0 EcoBoost Connected	Vehicle length (cm):	
License plate:	H178VT	Vehicle width (cm):	
Report code:	7076	Vehicle height (cm):	
Chassis number:	WF0JXXGAHJLC07076	(GAHJLC07076 Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	23/06/2020	Power(kw):	70
First NL reg.:	23/06/2020	Transmission	Manual
Color:	White Metallic	Number of gears	6
Weight (kg)(kg):	1164	Displacement(cc):	998
Empty weight(kg):	1064	Number of cylinders:	3
Wheelbase (cm)(cm):	249	Fuel type:	Petrol
Top speed (km/h):	180	Fuel tank capacity:	
Cons. in the city (I/100 km):	5	EU category:	Euro 6
Cons. outside the city (I/100 km):	3.6	Energy label:	Α
Avarage consumption (I/100 km):	arage consumption (I/100 km): 4.1		
Acceleration (s):	10.9	CO2 (q/km):	94
Cargo space (I):	1164	Nb. of Axles:	2
Perm. max weight (kg):	1690	APK date:	10/07/2026

## 🚓 opties

- Daytime running lights
- Licht Sensor
- Towing hook
- Anti-lock braking system
- ABS
- Airbag(s)
- 33333333333 Audio
- Central locking system
- Power steering
- Front seats adjustable in height
- Multifunctional steering wheel

- Remote central locking
- Halogen headlights
- LED rear lights
- Exterior mirrors in car body color
- 22222 Rain sensor
- Rear wiper
- Luggage cover
- USB connection
- DAB+
- Bluetooth car kit
  - Radio

- WiFi
  Cruise control
  Airconditioning
  Large screen navigation
  Electrically operated rear windows
  Electrically adjustable mirrors
  Audio control on the steering wheel
  Leather steering wheel

- Leather steering wheel
- Lane assistance

### 🗱 Tires

Tire position:	Tire	Wheel	Tire size:	Tire brand:	Tire profile depth (mm):
position:	type:	type:			
Tire left front	Winter	Steel	195/55 R16	Hankook	6
Tire left rear	Winter	Steel	195/55 R16	Hankook	6
Tire right front	Winter	Steel	195/55 R16	Hankook	6
Tire right rear	Winter	Steel	195/55 R16	Hankook	6

# **Additional information**

No. of keys:	1 Luxury key	Instruction booklet	✓ Airco works
Interior color:	Black	Maintenance booklet:	<b>⊘</b> Odorless
Upholstery:	Stof		Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	<b>☑</b> Display ok
No. of headrests:	5	Last turn mileage(km):	Vehicle special usage (None)

## **A** Cleaning

- Clean inside (Interior is clean)
- Clean outside (Polishing)







Front bumper - Scratch



Rear bumper - Scratch



Brandgat bestuurdersstoel

Damages

Acceptable

**¢**<sup>a</sup> Extra options






























































# AUTOF CTOR