



| | | | |
|------------------------------------|---|----------------------|------------|
| Brand: | Peugeot | Mileage(km): | 160263 |
| Model: | 2008 | Number of doors: | 5 |
| Model type: | 1.2 PureTech Blue Lease Active | Vehicle length (cm): | |
| License plate: | K755KD | Vehicle width (cm): | |
| Report code: | 6577 | Vehicle height (cm): | |
| Chassis number: | VR3USHNKKLJ866577 | Vehicle body type: | |
| Type of vehicle: | Luxury | Traction: | Front |
| First int. reg.: | 30/01/2021 | Power(kw): | 75 |
| First NL req.: | 30/01/2021 | Transmission | Manual |
| Color: | White <input type="checkbox"/> Metallic | Number of gears | 6 |
| Weight (kg)(kg): | 1263 | Displacement(cc): | 1199 |
| Empty weight(kg): | 1163 | Number of cylinders: | 3 |
| Wheelbase (cm)(cm): | 261 | Fuel type: | Petrol |
| Top speed (km/h): | 183 | Fuel tank capacity: | |
| Cons. in the city (l/100 km): | 5.5 | EU category: | Euro 6 |
| Cons. outside the city (l/100 km): | 4 | Energy label: | B |
| Average consumption (l/100 km): | 4.6 | NL Tax Rate %: | |
| Acceleration (s): | 12 | CO2 (g/km): | 105 |
| Cargo space (l): | 1263 | Nb. of Axles: | 2 |
| Perm. max weight (kg): | 1710 | APK date: | 30/01/2027 |

opties

- | | | |
|--|--|---|
| <input checked="" type="checkbox"/> Daytime running lights | <input checked="" type="checkbox"/> LED rear lights | <input checked="" type="checkbox"/> WiFi |
| <input checked="" type="checkbox"/> Licht Sensor | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Cruise control |
| <input checked="" type="checkbox"/> bots waarschuwing systeem | <input checked="" type="checkbox"/> Exterior mirrors with step light | <input checked="" type="checkbox"/> Airconditioning |
| <input checked="" type="checkbox"/> Anti-lock braking system | <input checked="" type="checkbox"/> Rain sensor | <input checked="" type="checkbox"/> Climate control |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Climate control (analog) |
| <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Climate control (digital) |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> Rear-seat folding (equal parts) | <input checked="" type="checkbox"/> Large screen navigation |
| <input checked="" type="checkbox"/> Central locking system | <input checked="" type="checkbox"/> Rear-seat folding (unequal parts) | <input checked="" type="checkbox"/> Electrically operated rear windows |
| <input checked="" type="checkbox"/> Fog lamps | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Start/stop system | <input checked="" type="checkbox"/> iPod connection | <input checked="" type="checkbox"/> Electrically folding mirrors |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> USB connection | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> Bluetooth streaming | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> DAB+ | <input checked="" type="checkbox"/> Leather steering wheel |
| <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> Bluetooth car kit | <input checked="" type="checkbox"/> Lane assistance |
| <input checked="" type="checkbox"/> LED headlights | <input checked="" type="checkbox"/> Radio | <input checked="" type="checkbox"/> Pedestrian safety system |

Tires

| Tire position: | Tire type: | Wheel type: | Tire size: | Tire brand: | Tire profile depth (mm): |
|------------------|------------|-------------|------------|-------------|--------------------------|
| Tire left front | Winter | Steel | 215/65 R16 | Vredestein | 5 |
| Tire left rear | Winter | Steel | 215/65 R16 | Vredestein | 5 |
| Tire right front | Winter | Steel | 215/65 R16 | Vredestein | 5 |
| Tire right rear | Winter | Steel | 215/65 R16 | Vredestein | 5 |

Additional information

| | | | | |
|-------------------|-------|-------------------------------------|--|--|
| No. of keys: | 2 | <input type="checkbox"/> Luxury key | <input type="checkbox"/> Instruction booklet | <input checked="" type="checkbox"/> Airco works |
| Interior color: | Black | Maintenance booklet: | (serviceboekje (papier)) | <input checked="" type="checkbox"/> Odorless |
| Upholstery: | Stof | | | <input checked="" type="checkbox"/> Clean inside (Interior is clean) |
| No. of seats: | 5 | Stamp date: | 05/01/2024 | <input checked="" type="checkbox"/> Display ok |
| No. of headrests: | 5 | Last turn mileage(km): | 111667 | <input checked="" type="checkbox"/> Vehicle special usage (None) |

Cleaning

- ☒ Clean inside (Interior is clean)
- ☒ Clean outside (Polishing)

🔧 Damages

⊕ Not acceptable



Front left door - Restyle dent



Tailgate/ lid - Dent

🔧 Damages

⊕ Acceptable

⚙️ Extra options



