



Brand:	Opel	Mileage(km):	191414
Model:	Astra	Number of doors:	5
Model type:	1.5 CDTI Business Elegance LED	Vehicle length (cm):	
License plate:	R547HF	Vehicle width (cm):	
Report code:	0901	Vehicle height (cm):	
Chassis number:	VXKFBYHZLN1020901	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	05/09/2022	Power(kw):	96
First NL req.:	05/09/2022	Transmission	Manual
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears	6
Weight (kg)(kg):	1424	Displacement(cc):	1498
Empty weight(kg):	1324	Number of cylinders:	4
Wheelbase (cm)(cm):	268	Fuel type:	Diesel
Top speed (km/h):	209	Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	A
Average consumption (l/100 km):		NL Tax Rate %:	
Acceleration (s):	10.6	CO2 (g/km):	1
Cargo space (l):	1424	Nb. of Axles:	2
Perm. max weight (kg):	1920	APK date:	05/09/2025

opties

<input checked="" type="checkbox"/> Alloy wheels	<input checked="" type="checkbox"/> Exterior mirrors in car body color	<input checked="" type="checkbox"/> Large screen navigation
<input checked="" type="checkbox"/> Digital dashboard	<input checked="" type="checkbox"/> Privacy glass	<input checked="" type="checkbox"/> Keyless entry
<input checked="" type="checkbox"/> Daytime running lights	<input checked="" type="checkbox"/> Rain sensor	<input checked="" type="checkbox"/> Keyless entry/start/stop
<input checked="" type="checkbox"/> Licht Sensor	<input checked="" type="checkbox"/> Rear wiper	<input checked="" type="checkbox"/> Keyless start/stop
<input checked="" type="checkbox"/> bots waarschuwing systeem	<input checked="" type="checkbox"/> Rear view camera	<input checked="" type="checkbox"/> Electrically operated rear windows
<input checked="" type="checkbox"/> Anti-lock braking system	<input checked="" type="checkbox"/> Rear parking sensors	<input checked="" type="checkbox"/> Electrically operated front windows
<input checked="" type="checkbox"/> ABS	<input checked="" type="checkbox"/> Front parking sensors	<input checked="" type="checkbox"/> Electrically folding mirrors
<input checked="" type="checkbox"/> Airbag(s)	<input checked="" type="checkbox"/> Ski hatch	<input checked="" type="checkbox"/> Electrically adjustable mirrors
<input checked="" type="checkbox"/> Audio	<input checked="" type="checkbox"/> Luggage cover	<input checked="" type="checkbox"/> Electrically heated driver's seat
<input checked="" type="checkbox"/> bots herkenning systeem	<input checked="" type="checkbox"/> USB connection	<input checked="" type="checkbox"/> Electrically heated passenger seat
<input checked="" type="checkbox"/> Central locking system	<input checked="" type="checkbox"/> DAB+	<input checked="" type="checkbox"/> Central armrest front
<input checked="" type="checkbox"/> Fog lamps	<input checked="" type="checkbox"/> Bluetooth car kit	<input checked="" type="checkbox"/> Extendable passenger seat
<input checked="" type="checkbox"/> Start/stop system	<input checked="" type="checkbox"/> Radio	<input checked="" type="checkbox"/> Extendable driver's seat
<input checked="" type="checkbox"/> Power steering	<input checked="" type="checkbox"/> Cruise control (adaptive)	<input checked="" type="checkbox"/> Adjustable lumbar support driver's seat
<input checked="" type="checkbox"/> Front seats adjustable in height	<input checked="" type="checkbox"/> Cruise control	<input checked="" type="checkbox"/> Adjustable lumbar support passenger seat
<input checked="" type="checkbox"/> Multifunctional steering wheel	<input checked="" type="checkbox"/> Airconditioning	<input checked="" type="checkbox"/> Audio control on the steering wheel
<input checked="" type="checkbox"/> Remote central locking	<input checked="" type="checkbox"/> Airconditioning in the back	<input checked="" type="checkbox"/> Leather steering wheel
<input checked="" type="checkbox"/> Metallic finish	<input checked="" type="checkbox"/> Climate control	<input checked="" type="checkbox"/> Heated steering wheel
<input checked="" type="checkbox"/> LED headlights	<input checked="" type="checkbox"/> Climate control (digital)	<input checked="" type="checkbox"/> Lane assistance
<input checked="" type="checkbox"/> LED rear lights	<input checked="" type="checkbox"/> Climate control (L/R separated)	<input checked="" type="checkbox"/> Pedestrian safety system

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Winter	Alloy	225/45 R17	Vredestein	3
Tire left rear	Winter	Alloy	225/45 R17	Vredestein	5
Tire right front	Winter	Alloy	225/45 R17	Vredestein	8
Tire right rear	Winter	Alloy	225/45 R17	Vredestein	5

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Grey	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Half stof/leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	30/08/2024	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	145739	<input checked="" type="checkbox"/> Vehicle special usage (None)

⚠ Cleaning

☒ Clean inside (Interior is clean)

☐ Clean outside

🔧 Damages

⊕ Not acceptable



Front left rim - Scratch



Rear left rim - Scratch



Front right rim - Scratch



Rear right rim - Scratch



Right sill - Dent



Rear bumper - Scratch



Left C- column - Restyle dent



Front left door - Scratch

🔧 Damages

⊕ Acceptable

⚙ Extra options





