



Brand:	Opel	Mileage(km):	88310
Model:	Grandland	Number of doors:	5
Model type:	1.2 Aut. Turbo Level 4 Org.NL Winterpakket Trekhaak	Vehicle length (cm):	
License plate:	S904PN	Vehicle width (cm):	
Report code:	7347	Vehicle height (cm):	
Chassis number:	W0VZRHNS1P6007347	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	17/03/2023	Power(kw):	96
First NL reg.:	17/03/2023	Transmission	Automatic
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears	8
Weight (kg)(kg):	1461	Displacement(cc):	1199
Empty weight(kg):	1361	Number of cylinders:	3
Wheelbase (cm)(cm):	268	Fuel type:	Petrol
Top speed (km/h):	196	Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	C
Average consumption (l/100 km):		NL Tax Rate %:	
Acceleration (s):	10.3	CO2 (g/km):	1
Cargo space (l):	1461	Nb. of Axles:	2
Perm. max weight (kg):	2000	APK date:	17/03/2027

opties

<input checked="" type="checkbox"/> Alloy wheels	<input checked="" type="checkbox"/> Rain sensor	<input checked="" type="checkbox"/> Large screen navigation
<input checked="" type="checkbox"/> Digital dashboard	<input checked="" type="checkbox"/> Rear wiper	<input checked="" type="checkbox"/> Electrically operated rear windows
<input checked="" type="checkbox"/> Daytime running lights	<input checked="" type="checkbox"/> Rear parking sensors	<input checked="" type="checkbox"/> Electrically operated front windows
<input checked="" type="checkbox"/> Licht Sensor	<input checked="" type="checkbox"/> Front parking sensors	<input checked="" type="checkbox"/> Electrically folding mirrors
<input checked="" type="checkbox"/> Towing hook	<input checked="" type="checkbox"/> Towbar with fixed ball	<input checked="" type="checkbox"/> Electrically adjustable mirrors
<input checked="" type="checkbox"/> bots waarschuwing systeem	<input checked="" type="checkbox"/> Rear-seat folding (equal parts)	<input checked="" type="checkbox"/> Electrically heated driver's seat
<input checked="" type="checkbox"/> Anti-lock braking system	<input checked="" type="checkbox"/> Rear-seat folding (unequal parts)	<input checked="" type="checkbox"/> Electrically heated passenger seat
<input checked="" type="checkbox"/> ABS	<input checked="" type="checkbox"/> Ski hatch	<input checked="" type="checkbox"/> Central armrest front
<input checked="" type="checkbox"/> Airbag(s)	<input checked="" type="checkbox"/> Luggage cover	<input checked="" type="checkbox"/> Extendable passenger seat
<input checked="" type="checkbox"/> Audio	<input checked="" type="checkbox"/> USB connection	<input checked="" type="checkbox"/> Extendable driver's seat
<input checked="" type="checkbox"/> Central locking system	<input checked="" type="checkbox"/> Bluetooth streaming	<input checked="" type="checkbox"/> Adjustable lumbar support driver's seat
<input checked="" type="checkbox"/> Start/stop system	<input checked="" type="checkbox"/> DAB+	<input checked="" type="checkbox"/> Adjustable lumbar support passenger seat
<input checked="" type="checkbox"/> Power steering	<input checked="" type="checkbox"/> Bluetooth car kit	<input checked="" type="checkbox"/> Audio control on the steering wheel
<input checked="" type="checkbox"/> Front seats adjustable in height	<input checked="" type="checkbox"/> Radio	<input checked="" type="checkbox"/> Leather sports steering wheel
<input checked="" type="checkbox"/> Multifunctional steering wheel	<input checked="" type="checkbox"/> Cruise control	<input checked="" type="checkbox"/> Leather steering wheel
<input checked="" type="checkbox"/> Remote central locking	<input checked="" type="checkbox"/> Airconditioning	<input checked="" type="checkbox"/> Switch flippers
<input checked="" type="checkbox"/> Metallic finish	<input checked="" type="checkbox"/> Airconditioning in the back	<input checked="" type="checkbox"/> Heated steering wheel
<input checked="" type="checkbox"/> LED headlights	<input checked="" type="checkbox"/> Climate control	<input checked="" type="checkbox"/> Lane assistance
<input checked="" type="checkbox"/> LED rear lights	<input checked="" type="checkbox"/> Climate control (analog)	<input checked="" type="checkbox"/> Pedestrian safety system
<input checked="" type="checkbox"/> Exterior mirrors in car body color	<input checked="" type="checkbox"/> Climate control (digital)	
<input checked="" type="checkbox"/> Privacy glass	<input checked="" type="checkbox"/> Climate control (L/R separated)	

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	225/55 R18	Michelin	3
Tire left rear	Summer	Alloy	225/55 R18	Michelin	4
Tire right front	Summer	Alloy	225/55 R18	Michelin	3
Tire right rear	Summer	Alloy	225/55 R18	Michelin	4

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Half stof/leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	27/10/2023	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	25054	<input checked="" type="checkbox"/> Vehicle special usage (None)

⚠ Cleaning

☒ Clean inside (Interior is clean)

☐ Clean outside

🔧 Damages

⊕ Not acceptable





Bonnet - Stone chippings


🔧 Damages

⊕ Acceptable

⚙ Extra options







AUTOF[▲]CTOR
SOFTWARE FOR AUTOMOTIVE