



<b>Brand:</b>	Opel	<b>Mileage(km):</b>	158470
<b>Model:</b>	Grandland X	<b>Number of doors:</b>	5
<b>Model type:</b>	1.2 Turbo Business Executive	<b>Vehicle length (cm):</b>	
<b>License plate:</b>	TT403X	<b>Vehicle width (cm):</b>	
<b>Report code:</b>	6332	<b>Vehicle height (cm):</b>	
<b>Chassis number:</b>	W0VZRHNS0KS016332	<b>Vehicle body type:</b>	
<b>Type of vehicle:</b>	Luxury	<b>Traction:</b>	Front
<b>First int. reg.:</b>	30/10/2018	<b>Power(kw):</b>	96
<b>First NL req.:</b>	30/10/2018	<b>Transmission</b>	Manual
<b>Color:</b>	Red <input checked="" type="checkbox"/> <b>Metallic</b>	<b>Number of gears</b>	6
<b>Weight (kg)(kg):</b>	1370	<b>Displacement(cc):</b>	1199
<b>Empty weight(kg):</b>	1270	<b>Number of cylinders:</b>	3
<b>Wheelbase (cm)(cm):</b>	268	<b>Fuel type:</b>	Petrol
<b>Top speed (km/h):</b>	188	<b>Fuel tank capacity:</b>	
<b>Cons. in the city (l/100 km):</b>	6.1	<b>EU category:</b>	Euro 6
<b>Cons. outside the city (l/100 km):</b>	4.9	<b>Energy label:</b>	B
<b>Average consumption (l/100 km):</b>	5.3	<b>NL Tax Rate %:</b>	
<b>Acceleration (s):</b>	10.1	<b>CO2 (g/km):</b>	121
<b>Cargo space (l):</b>	1370	<b>Nb. of Axles:</b>	2
<b>Perm. max weight (kg):</b>	1900	<b>APK date:</b>	30/10/2026

## opties

<input checked="" type="checkbox"/> Alloy wheels	<input checked="" type="checkbox"/> Privacy glass	<input checked="" type="checkbox"/> Climate control (analog)
<input checked="" type="checkbox"/> Daytime running lights	<input checked="" type="checkbox"/> Rain sensor	<input checked="" type="checkbox"/> Climate control (digital)
<input checked="" type="checkbox"/> Licht Sensor	<input checked="" type="checkbox"/> Rear wiper	<input checked="" type="checkbox"/> Climate control (L/R separated)
<input checked="" type="checkbox"/> Towing hook	<input checked="" type="checkbox"/> Rear view camera	<input checked="" type="checkbox"/> Large screen navigation
<input checked="" type="checkbox"/> bots waarschuwing systeem	<input checked="" type="checkbox"/> Rear parking sensors	<input checked="" type="checkbox"/> Keyless entry
<input checked="" type="checkbox"/> Anti-lock braking system	<input checked="" type="checkbox"/> Front parking sensors	<input checked="" type="checkbox"/> Keyless entry/start/stop
<input checked="" type="checkbox"/> ABS	<input checked="" type="checkbox"/> Towbar with fixed ball	<input checked="" type="checkbox"/> Keyless start/stop
<input checked="" type="checkbox"/> Airbag(s)	<input checked="" type="checkbox"/> Rear-seat folding (equal parts)	<input checked="" type="checkbox"/> Electrically operated rear windows
<input checked="" type="checkbox"/> Audio	<input checked="" type="checkbox"/> Rear-seat folding (unequal parts)	<input checked="" type="checkbox"/> Electrically operated front windows
<input checked="" type="checkbox"/> Central locking system	<input checked="" type="checkbox"/> Luggage cover	<input checked="" type="checkbox"/> Electrically folding mirrors
<input checked="" type="checkbox"/> Start/stop system	<input checked="" type="checkbox"/> Trunk opens electrically	<input checked="" type="checkbox"/> Electrically adjustable mirrors
<input checked="" type="checkbox"/> Power steering	<input checked="" type="checkbox"/> USB connection	<input checked="" type="checkbox"/> Electrically heated driver's seat
<input checked="" type="checkbox"/> Front seats adjustable in height	<input checked="" type="checkbox"/> Bluetooth streaming	<input checked="" type="checkbox"/> Electrically heated passenger seat
<input checked="" type="checkbox"/> Multifunctional steering wheel	<input checked="" type="checkbox"/> DAB+	<input checked="" type="checkbox"/> Central armrest front
<input checked="" type="checkbox"/> Remote central locking	<input checked="" type="checkbox"/> Bluetooth car kit	<input checked="" type="checkbox"/> Audio control on the steering wheel
<input checked="" type="checkbox"/> Metallic finish	<input checked="" type="checkbox"/> Radio	<input checked="" type="checkbox"/> Leather steering wheel
<input checked="" type="checkbox"/> Halogen headlights	<input checked="" type="checkbox"/> Cruise control	<input checked="" type="checkbox"/> Heated steering wheel
<input checked="" type="checkbox"/> LED rear lights	<input checked="" type="checkbox"/> Airconditioning	<input checked="" type="checkbox"/> Lane assistance
<input checked="" type="checkbox"/> Exterior mirrors in car body color	<input checked="" type="checkbox"/> Airconditioning in the back	<input checked="" type="checkbox"/> Pedestrian safety system
<input checked="" type="checkbox"/> Exterior mirrors with step light	<input checked="" type="checkbox"/> Climate control	<input checked="" type="checkbox"/> Dead angle assistance

## Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Winter	Alloy	225/55 R18	Goodyear	7
Tire left rear	Winter	Alloy	225/55 R18	Goodyear	8
Tire right front	Winter	Alloy	225/55 R18	Goodyear	7
Tire right rear	Winter	Alloy	225/55 R18	Goodyear	8

## Additional information

<b>No. of keys:</b>	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
<b>Interior color:</b>	Black	<b>Maintenance booklet:</b>	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
<b>Upholstery:</b>	Half stof/leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
<b>No. of seats:</b>	5	<b>Stamp date:</b>	04/09/2023	<input checked="" type="checkbox"/> Display ok
<b>No. of headrests:</b>	5	<b>Last turn mileage(km):</b>	45934	<input checked="" type="checkbox"/> Vehicle special usage (None)

## ⚠ Cleaning

- ☒ Clean inside (Interior is clean)
- ☒ Clean outside (Cleaning)

## 🔧 Damages

⊕ Not acceptable



Front right rim - Scratch



Front left door - Dent



Rear bumper - Paint repair



Rear right screen - Restyle dent



Rear right door - Paint repair



Front left door - Paint repair



Bonnet - Bird droppings



Roof - Restyle dent



Stuur beschadigd


## 🔧 Damages

⊕ Acceptable

## ⚙ Extra options









AUTOF<sup>▲</sup>CTOR  
SOFTWARE FOR AUTOMOTIVE