



Brand:	Fiat	Mileage(km):	58251
Model:	Talento	Number of doors:	5
Model type:	2.0 MultiJet L2H1 SX DC	Vehicle length (cm):	
License plate:	VFG81P	Vehicle width (cm):	
Report code:	2021	Vehicle height (cm):	
Chassis number:	ZFAFFL008K5112021	Vehicle body type:	
Type of vehicle:	Commercial	Traction:	Front
First int. reg.:	28/12/2020	Power(kw):	107
First NL reg.:	28/12/2020	Transmission	Manual
Color:	<input checked="" type="checkbox"/> Metallic	Number of gears	6
Weight (kg)(kg):	2001	Displacement(cc):	1997
Empty weight(kg):	1901	Number of cylinders:	4
Wheelbase (cm)(cm):	350	Fuel type:	Diesel
Top speed (km/h):	176	Fuel tank capacity:	
Cons. in the city (l/100 km):	6	EU category:	Euro 6
Cons. outside the city (l/100 km):	6	Energy label:	
Average consumption (l/100 km):	6	NL Tax Rate %:	
Acceleration (s):	11.9	CO2 (g/km):	150
Cargo space (l):	2001	Nb. of Axles:	2
Perm. max weight (kg):	3070	APK date:	28/12/2025
Loading space length (cm):		Towing Capacity (kg):	
Loading space width (cm):		Load capacity (kg):	1169
Loading space height (cm):		Trailer Weight (kg):	

Hydraulic Installation:

opties

<input checked="" type="checkbox"/> Alloy wheels	<input checked="" type="checkbox"/> Privacy glass	<input checked="" type="checkbox"/> Bluetooth streaming
<input checked="" type="checkbox"/> Daytime running lights	<input checked="" type="checkbox"/> Rear wiper	<input checked="" type="checkbox"/> DAB+
<input checked="" type="checkbox"/> Towing hook	<input checked="" type="checkbox"/> Rear view camera	<input checked="" type="checkbox"/> Bluetooth car kit
<input checked="" type="checkbox"/> Anti-lock braking system	<input checked="" type="checkbox"/> Rear parking sensors	<input checked="" type="checkbox"/> Radio
<input checked="" type="checkbox"/> ABS	<input checked="" type="checkbox"/> Towbar with fixed ball	<input checked="" type="checkbox"/> Cruise control
<input checked="" type="checkbox"/> Airbag(s)	<input checked="" type="checkbox"/> 2-seater driver's seat	<input checked="" type="checkbox"/> Airconditioning
<input checked="" type="checkbox"/> Audio	<input checked="" type="checkbox"/> Rear doors	<input checked="" type="checkbox"/> Climate control
<input checked="" type="checkbox"/> Central locking system	<input checked="" type="checkbox"/> Double cabin with belts	<input checked="" type="checkbox"/> Climate control (analog)
<input checked="" type="checkbox"/> Place to lie down	<input checked="" type="checkbox"/> Covered load space	<input checked="" type="checkbox"/> Large screen navigation
<input checked="" type="checkbox"/> Start/stop system	<input checked="" type="checkbox"/> Loading area with concrete plywood floor	<input checked="" type="checkbox"/> Electrically operated front windows
<input checked="" type="checkbox"/> Power steering	<input checked="" type="checkbox"/> Cargo area with doors	<input checked="" type="checkbox"/> Electrically adjustable mirrors
<input checked="" type="checkbox"/> Front seats adjustable in height	<input checked="" type="checkbox"/> Loading area with lighting	<input checked="" type="checkbox"/> Central armrest front
<input checked="" type="checkbox"/> Multifunctional steering wheel	<input checked="" type="checkbox"/> Sliding door on the right	<input checked="" type="checkbox"/> Adjustable lumbar support driver's seat
<input checked="" type="checkbox"/> Remote central locking	<input checked="" type="checkbox"/> Sidebars	<input checked="" type="checkbox"/> Adjustable lumbar support passenger seat
<input checked="" type="checkbox"/> Metallic finish	<input checked="" type="checkbox"/> Full partition	<input checked="" type="checkbox"/> Leather steering wheel
<input checked="" type="checkbox"/> Halogen headlights	<input checked="" type="checkbox"/> Aux connection	
<input checked="" type="checkbox"/> Exterior mirrors in car body color	<input checked="" type="checkbox"/> USB connection	

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	215/60 R17	Vredestein	4
Tire left rear	Summer	Alloy	215/60 R17	Goodyear	6
Tire right front	Summer	Alloy	215/60 R17	Vredestein	4
Tire right rear	Summer	Alloy	215/60 R17	Goodyear	6

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:		<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:		<input checked="" type="checkbox"/> Display ok

No. of headrests:

5

Last turn mileage(km):

☒ Vehicle special usage (Taxi)

Cleaning

☒ Clean inside (Interior is clean)

☐ Clean outside

Damages

 Not acceptable



Front bumper - Scratch



Left sill - Scratch



Rear bumper - Scratch



Roof - Restyle dent






Right sill - Scratch

Damages

 Acceptable

Extra options







AUTOF▲CTOR
SOFTWARE FOR AUTOMOTIVE