

#### Inspected by: Rob Datema



Brand:	Volvo	Mileage(km):	346792
Model:	S60	Number of doors:	4
Model type:	2.4 Edition	Vehicle length (cm):	
License plate:	65JPKP	Vehicle width (cm):	
Report code:	6835	Vehicle height (cm):	
Chassis number:	YV1RS65P922176835	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	09/07/2002	Power(kw):	103
First NL reg.:	09/07/2002	Transmission	Automatic
Color:	Blue Metallic	Number of gears	
Weight (kg)(kg):	1571	Displacement(cc):	2435
Empty weight(kg):	1471	Number of cylinders:	5
Wheelbase (cm)(cm):	272	Fuel type:	Petrol
Top speed (km/h):	205	Fuel tank capacity:	
Cons. in the city (I/100 km):	13.5	EU category:	Euro 4
Cons. outside the city (I/100 km):	7	Energy label:	D
Avarage consumption (I/100 km):	9.4	NL Tax Rate %:	
Acceleration (s):	11.1	CO2 (q/km):	225
Cargo space (I):	1571	Nb. of Axles:	2
Perm. max weight (kg):	2000	APK date:	03/07/2025

#### 🚓 opties

- Alloy wheels
- Daytime running lights
- Towing hook
- Anti-lock braking system
- ABS
- Airbag(s)
- Audio
- 33333333333 Central locking system
- Fog lamps
- Power steering
- Front seats adjustable in height

- Multifunctional steering wheel
- Remote central locking
- 11111 Metallic finish
- Halogen headlights
- Exterior mirrors in car body color
- Towbar with fixed ball ~
- ~ Aux connection
- iPod connection
- $\overline{\mathbf{v}}$ USB connection
- Radio/CD player
- Radio/CD/MP3 player

- Bluetooth car kit
- Cruise control
- Airconditioning
- Climate control
- Climate control (analog)
- Climate control (L/R separated)
- Electrically operated rear windows Electrically operated front windows
- Electrically adjustable mirrors
- Central armrest front
- Leather steering wheel

## 🗱 Tires

Tire	Tire	Wheel	Tire size:	Tire brand:	Tire profile depth (mm):
position:	type:	type:			
Tire left front	Summer	Alloy	205/55 R16	Vredestein	3
Tire left rear	Summer	Alloy	205/55 R16	Vredestein	4
Tire right front	Summer	Alloy	205/55 R16	Vredestein	3
Tire right rear	Summer	Allov	205/55 R16	Vredestein	4

### A Additional information

	No. of keys:	1 Luxury key	Luxury key Instruction booklet		Airco works
	Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	Odorless
	Upholstery:	Half stof/leder			Clean inside (Cleaning)
	No. of seats:	5	Stamp date:	15/01/2025	<b>☑</b> Display ok
	No. of headrests:	5	Last turn mileage(km):	345294	▼ Vehicle special usage (None)

#### **A** Cleaning

- Clean inside (Cleaning)
- Clean outside (Polishing)



Voertuig rondom - User damage according to km and



Voertuig rondom - User damage according to km and



Bonnet - Hail damage



Roof - Hail damage



Front bumper - Ontzet



Scheur bestuurdersstoel en krassen in deurpaneel



Scheur bestuurdersstoel en krassen in deurpaneel

Acceptable

Damages

🗱 Extra options





























































# AUTOF CTOR