



Brand:	Opel	Mileage(km):	102382
Model:	Astra Sports Tourer	Number of doors:	5
Model type:	1.2 Business Edition	Vehicle length (cm):	
License plate:	K938KS	Vehicle width (cm):	
Report code:	5936	Vehicle height (cm):	
Chassis number:	W0VBD8ER3M8005936	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	08/01/2021	Power(kw):	81
First NL reg.:	08/01/2021	Transmission	Manual
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears	6
Weight (kg)(kg):	1355	Displacement(cc):	1199
Empty weight(kg):	1255	Number of cylinders:	3
Wheelbase (cm)(cm):	266	Fuel type:	Petrol
Top speed (km/h):	200	Fuel tank capacity:	
Cons. in the city (l/100 km):	5.5	EU category:	Euro 6
Cons. outside the city (l/100 km):	3.9	Energy label:	A
Average consumption (l/100 km):	4.5	NL Tax Rate %:	
Acceleration (s):	10.6	CO2 (g/km):	102
Cargo space (l):	1355	Nb. of Axles:	2
Perm. max weight (kg):	1870	APK date:	08/01/2027

opties

- | | | |
|--|--|---|
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> USB connection |
| <input checked="" type="checkbox"/> Daytime running lights | <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> DAB+ |
| <input checked="" type="checkbox"/> Licht Sensor | <input checked="" type="checkbox"/> Roof rail (black) | <input checked="" type="checkbox"/> Bluetooth car kit |
| <input checked="" type="checkbox"/> Anti-lock braking system | <input checked="" type="checkbox"/> Metallic finish | <input checked="" type="checkbox"/> Cruise control |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> LED headlights | <input checked="" type="checkbox"/> Airconditioning |
| <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> LED rear lights | <input checked="" type="checkbox"/> Large screen navigation |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Electrically operated rear windows |
| <input checked="" type="checkbox"/> Central locking system | <input checked="" type="checkbox"/> Rain sensor | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Fog lamps | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> Luggage cover | |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Winter	Alloy	205/55 R16	Vredestein	5
Tire left rear	Winter	Alloy	205/55 R16	Vredestein	5
Tire right front	Winter	Alloy	205/55 R16	Vredestein	5
Tire right rear	Winter	Alloy	205/55 R16	Bridgestone	5

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	10/10/2023	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	70703	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- ☒ Clean inside (Interior is clean)
- ☒ Clean outside (Polishing)

Damages

☒ Not acceptable



Front right rim - Scratch



Front left door - Scratch



Rear left screen - Restyle dent



Rear bumper - Scratch



Rear right screen - Restyle dent



Right sill - Dent



Left B- column - Scratch

🔧 Damages

🔧 Acceptable

⚙️ Extra options





