



Brand:	Ford	Mileage(km):	149568
Model:	Fiesta	Number of doors:	5
Model type:	1.1 Trend   Org.NL	Vehicle length (cm):	
License plate:	SN964K	Vehicle width (cm):	
Report code:	6491	Vehicle height (cm):	
Chassis number:	WF0JXXGAHJHD06491	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	15/05/2018	Power(kw):	52
First NL reg.:	15/05/2018	Transmission	Manual
Color:	White <input type="checkbox"/> Metallic	Number of gears	
Weight (kg)(kg):	1135	Displacement(cc):	1084
Empty weight(kg):	1035	Number of cylinders:	3
Wheelbase (cm)(cm):	249	Fuel type:	Petrol
Top speed (km/h):	160	Fuel tank capacity:	
Cons. in the city (l/100 km):	5.6	EU category:	Euro 6
Cons. outside the city (l/100 km):	3.7	Energy label:	B
Average consumption (l/100 km):	4.4	NL Tax Rate %:	
Acceleration (s):	14.9	CO2 (g/km):	101
Cargo space (l):	1135	Nb. of Axles:	2
Perm. max weight (kg):	1645	APK date:	22/02/2026

## opties

- |  |  |   |
|--|--|---|
| <input checked="" type="checkbox"/> Daytime running lights           | <input checked="" type="checkbox"/> Remote central locking             | <input checked="" type="checkbox"/> Bluetooth car kit                   |
| <input checked="" type="checkbox"/> Licht Sensor                     | <input checked="" type="checkbox"/> Halogen headlights                 | <input checked="" type="checkbox"/> Radio                               |
| <input checked="" type="checkbox"/> Anti-lock braking system         | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Cruise control                      |
| <input checked="" type="checkbox"/> ABS                              | <input checked="" type="checkbox"/> Rear wiper                         | <input checked="" type="checkbox"/> Airconditioning                     |
| <input checked="" type="checkbox"/> Airbag(s)                        | <input checked="" type="checkbox"/> Rear parking sensors               | <input checked="" type="checkbox"/> Climate control                     |
| <input checked="" type="checkbox"/> Audio                            | <input checked="" type="checkbox"/> Rear-seat folding (equal parts)    | <input checked="" type="checkbox"/> Climate control (analog)            |
| <input checked="" type="checkbox"/> Central locking system           | <input checked="" type="checkbox"/> Rear-seat folding (unequal parts)  | <input checked="" type="checkbox"/> Large screen navigation             |
| <input checked="" type="checkbox"/> Start/stop system                | <input checked="" type="checkbox"/> Luggage cover                      | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Power steering                   | <input checked="" type="checkbox"/> USB connection                     | <input checked="" type="checkbox"/> Electrically adjustable mirrors     |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> Bluetooth streaming                | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Multifunctional steering wheel   | <input checked="" type="checkbox"/> DAB+                               | <input checked="" type="checkbox"/> Lane assistance                     |

## Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	All weather	Steel	195/55 R16	Vredestein	7
Tire left rear	All weather	Steel	195/55 R16	Vredestein	6
Tire right front	All weather	Steel	195/55 R16	Vredestein	7
Tire right rear	All weather	Steel	195/55 R16	Vredestein	6

## Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	21/02/2024	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	131735	<input checked="" type="checkbox"/> Vehicle special usage (None)

## Cleaning

- ☒ Clean inside (Interior is clean)
- ☐ Clean outside

## Damages

⊗ Not acceptable



Front left screen - Paint repair



Bonnet - Paint repair



Front left screen - Paint repair



Front left door - Paint repair



Left tailgate - Break



Rear bumper - Paint repair



Left A- column - Dent

🔧 Damages

🔧 Acceptable

⚙️ Extra options







