



Brand:	Jeep	Mileage(km):	111136
Model:	Renegade	Number of doors:	5
Model type:	1.4 MultiAir Opening Edition Clima Cruise Winterpakket Trekhaak	Vehicle length (cm):	
License plate:	RR525T	Vehicle width (cm):	
Report code:	0705	Vehicle height (cm):	
Chassis number:	1C4BU0000FPB10705	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	30/12/2014	Power(kw):	103
First NL reg.:	06/01/2018	Transmission	Manual
Color:	White <input type="checkbox"/> Metallic	Number of gears	6
Weight (kg)(kg):	1395	Displacement(cc):	1368
Empty weight(kg):	1295	Number of cylinders:	4
Wheelbase (cm)(cm):	257	Fuel type:	Petrol
Top speed (km/h):	181	Fuel tank capacity:	
Cons. in the city (l/100 km):	7.6	EU category:	Euro 6
Cons. outside the city (l/100 km):	5.1	Energy label:	C
Average consumption (l/100 km):	6	NL Tax Rate %:	25
Acceleration (s):	10.9	CO2 (g/km):	140
Cargo space (l):	1395	Nb. of Axles:	2
Perm. max weight (kg):	1865	APK date:	26/10/2025

opties

- | | | |
|--|--|--|
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Halogen headlights | <input checked="" type="checkbox"/> Large screen navigation |
| <input checked="" type="checkbox"/> Daytime running lights | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Keyless entry |
| <input checked="" type="checkbox"/> Towing hook | <input checked="" type="checkbox"/> Privacy glass | <input checked="" type="checkbox"/> Keyless entry/start/stop |
| <input checked="" type="checkbox"/> Anti-lock braking system | <input checked="" type="checkbox"/> Rain sensor | <input checked="" type="checkbox"/> Keyless start/stop |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Electrically operated rear windows |
| <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Electrically folding mirrors |
| <input checked="" type="checkbox"/> Central locking system | <input checked="" type="checkbox"/> USB connection | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Fog lamps | <input checked="" type="checkbox"/> Bluetooth car kit | <input checked="" type="checkbox"/> Central armrest front |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> Cruise control | <input checked="" type="checkbox"/> Adjustable lumbar support driver's seat |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> Airconditioning | <input checked="" type="checkbox"/> Adjustable lumbar support passenger seat |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> Climate control (analog) | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> Climate control (digital) | <input checked="" type="checkbox"/> Leather steering wheel |
| <input checked="" type="checkbox"/> Roof rail (silver) | <input checked="" type="checkbox"/> Climate control (L/R separated) | |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
----------------	------------	-------------	------------	-------------	--------------------------

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Half stof/leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	04/09/2024	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	108153	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- ☒ Clean inside (Interior is clean)
- ☐ Clean outside

Damages

⊛ Not acceptable



Front bumper - Scratch



Front left door - Paint repair



Rear left door - Paint repair



Rear left screen - Paint repair







Windscreen - Pip

🔧 Damages

🔧 Acceptable

⚙️ Extra options







AUTOF[▲]CTOR
SOFTWARE FOR AUTOMOTIVE