



Brand:	Opel	Mileage(km):	127320
Model:	Astra	Number of doors:	5
Model type:	1.2 Edition Org.NL	Vehicle length (cm):	
License plate:	H626SH	Vehicle width (cm):	
Report code:	8942	Vehicle height (cm):	
Chassis number:	W0VBD6ER8LG038942	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	30/04/2020	Power(kw):	81
First NL reg.:	30/04/2020	Transmission	Manual
Color:	Blue <input checked="" type="checkbox"/> Metallic	Number of gears	6
Weight (kg)(kg):	1280	Displacement(cc):	1199
Empty weight(kg):	1180	Number of cylinders:	3
Wheelbase (cm)(cm):	266	Fuel type:	Petrol
Top speed (km/h):	200	Fuel tank capacity:	
Cons. in the city (l/100 km):	5.3	EU category:	Euro 6
Cons. outside the city (l/100 km):	3.8	Energy label:	A
Average consumption (l/100 km):	4.3	NL Tax Rate %:	
Acceleration (s):	10.4	CO2 (g/km):	99
Cargo space (l):	1280	Nb. of Axles:	2
Perm. max weight (kg):	1805	APK date:	30/04/2026

opties

- | | | |
|--|--|--|
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Halogen headlights | <input checked="" type="checkbox"/> Climate control (digital) |
| <input checked="" type="checkbox"/> Daytime running lights | <input checked="" type="checkbox"/> LED rear lights | <input checked="" type="checkbox"/> Climate control (L/R separated) |
| <input checked="" type="checkbox"/> Licht Sensor | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Large screen navigation |
| <input checked="" type="checkbox"/> Anti-lock braking system | <input checked="" type="checkbox"/> Rain sensor | <input checked="" type="checkbox"/> Electrically operated rear windows |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Rear view camera | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> Front parking sensors | <input checked="" type="checkbox"/> Central armrest front |
| <input checked="" type="checkbox"/> Central locking system | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Adjustable lumbar support driver's seat |
| <input checked="" type="checkbox"/> Fog lamps | <input checked="" type="checkbox"/> USB connection | <input checked="" type="checkbox"/> Adjustable lumbar support passenger seat |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> Bluetooth car kit | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> Cruise control | <input checked="" type="checkbox"/> Leather steering wheel |
| <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> Airconditioning | |
| <input checked="" type="checkbox"/> Metallic finish | <input checked="" type="checkbox"/> Climate control | |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	205/55 R16	Vredestein	1
Tire left rear	Summer	Alloy	205/55 R16	Vredestein	4
Tire right front	Summer	Alloy	205/55 R16	Vredestein	1
Tire right rear	Summer	Alloy	205/55 R16	Vredestein	4

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	03/04/2024	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	97119	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- ☒ Clean inside (Interior is clean)
- ☒ Clean outside (Polishing)

🔧 Damages

⊕ Not acceptable



Bonnet - Rust formation



Left sill - Dent



Right outside mirror - Scratch

🔧 Damages

⊕ Acceptable

⚙️ Extra options



