



Brand:	Toyota	Mileage(km):	80355
Model:	Аудо	Number of doors:	5
Model type:	1.0 VVT-i x-fun	Vehicle length (cm):	
License plate:	N409XJ	Vehicle width (cm):	
Report code:	9656	Vehicle height (cm):	
Chassis number:	JTDKGNEC30N679656	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	28/02/2022	Power(kw):	53
First NL reg.:	28/02/2022	Transmission	Manual
Color:	Grey 🌄 Metallic	Number of gears	5
Weight (kg)(kg):	915	Displacement(cc):	998
Empty weight(kg):	815	Number of cylinders:	3
Wheelbase (cm)(cm):	234	Fuel type:	Petrol
Top speed (km/h):	160	Fuel tank capacity:	
Cons. in the city (l/100 km):	4.3	EU category:	Euro 6
Cons. outside the city (I/100 km):	3.5	Energy label:	В
Avarage consumption (I/100 km):	3.8	NL Tax Rate %:	
Acceleration (s):	13.8	CO2 (q/km):	86
Cargo space (I):	915	Nb. of Axles:	2
Perm. max weight (kg):	1240	APK date:	28/02/2026

📽 opties

- Daytime running lights
- Anti-lock braking system ABS
- Airbag(s)
- Audio
- Central locking system
- Power steering
- Front seats adjustable in height Multifunctional steering wheel

\checkmark	Remote central locking
	Metallic finish
$\overline{}$	Halogen headlights
$\overline{}$	LED rear lights
$\overline{}$	Rear wiper
$\overline{}$	Removable rear window
$\overline{}$	Luggage cover
$\overline{}$	Aux connection
$\overline{}$	iPod connection

Removable rear windows

USB connection হাহাহাহাহ Bluetooth car kit

Radio

- Airconditioning
- Electrically operated front windows
- Audio control on the steering wheel
- Leather steering wheel

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Steel	165/65 R14	Vredestein	6
Tire left rear	Summer	Steel	165/65 R14	Vredestein	5
Tire right front	Summer	Steel	165/65 R14	Vredestein	6
Tire right rear	Summer	Steel	165/65 R14	Vredestein	5

Additional information

No. of keys:	2 🗌 Luxury key	Instruction booklet	Airco works
Interior color:	Black	Maintenance booklet:	Odorless
Upholstery:	Stof		Clean inside (Interior is clean)
No. of seats:	4	Stamp date:	Display ok
No. of headrests:	4	Last turn mileage(km):	Vehicle special usage (None)

▲ Cleaning


Clean inside (Interior is clean)


Clean outside (Polishing)

Damages

Not acceptable

Inspected by: Rob Datema







Г



