



Brand:	Subaru	Mileage(km):	210013
Model:	Impreza	Number of doors:	5
Model type:	Plus 2.0 GX AWD Automaat Org. NL 2e Eig. Zeer goed onderhouden!	Vehicle length (cm):	
License plate:	04NZFJ	Vehicle width (cm):	
Report code:	4650	Vehicle height (cm):	
Chassis number:	JF1GG9LR54G024650	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front+Rear
First int. reg.:	31/03/2004	Power(kw):	92
First NL reg.:	31/03/2004	Transmission	Automatic
Color:	Grey <input checked="" type="checkbox"/> Metallic	Number of gears	
Weight (kg)(kg):	1415	Displacement(cc):	1994
Empty weight(kg):	1315	Number of cylinders:	4
Wheelbase (cm)(cm):	253	Fuel type:	Petrol
Top speed (km/h):	179	Fuel tank capacity:	
Cons. in the city (l/100 km):	12.3	EU category:	Euro 3
Cons. outside the city (l/100 km):	6.5	Energy label:	E
Average consumption (l/100 km):	8.6	NL Tax Rate %:	
Acceleration (s):	12.7	CO2 (g/km):	206
Cargo space (l):	1415	Nb. of Axles:	2
Perm. max weight (kg):	1800	APK date:	14/06/2025

opties

- | | | |
|--|--|---|
| <input checked="" type="checkbox"/> Daytime running lights | <input checked="" type="checkbox"/> Roof rail (silver) | <input checked="" type="checkbox"/> Radio |
| <input checked="" type="checkbox"/> Towing hook | <input checked="" type="checkbox"/> Roof rail (black) | <input checked="" type="checkbox"/> Cruise control |
| <input checked="" type="checkbox"/> Anti-lock braking system | <input checked="" type="checkbox"/> Metallic finish | <input checked="" type="checkbox"/> Airconditioning |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Halogen headlights | <input checked="" type="checkbox"/> Climate control |
| <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Climate control (analog) |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> Privacy glass | <input checked="" type="checkbox"/> Electrically operated rear windows |
| <input checked="" type="checkbox"/> Central locking system | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Fog lamps | <input checked="" type="checkbox"/> Towbar with detachable ball | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> Rear-seat folding (equal parts) | <input checked="" type="checkbox"/> Sport seats |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> Rear-seat folding (unequal parts) | <input checked="" type="checkbox"/> Leather steering wheel |
| <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> Luggage cover | |
| <input checked="" type="checkbox"/> Sports package (exterior) | <input checked="" type="checkbox"/> CD changer | |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	All weather	Steel	195/60 R15	Goodyear	7
Tire left rear	All weather	Steel	195/60 R15	Goodyear	7
Tire right front	All weather	Steel	195/60 R15	Goodyear	7
Tire right rear	All weather	Steel	195/60 R15	Goodyear	7

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	04/04/2025	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	209793	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- ☒ Clean inside (Interior is clean)
- ☒ Clean outside (Cleaning)

🔧 Damages

⊕ Not acceptable



Front bumper - Scratch



Rear left door - Scratch



Front bumper - Ontzet



Left outside mirror - Scratch



Rear bumper - Scratch






Front left screen - Restyle dent

🔧 Damages

⊕ Acceptable

⚙️ Extra options







AUTOF[▲]CTOR
SOFTWARE FOR AUTOMOTIVE