



Brand:	Volkswagen	Mileage(km):	137449
Model:	Polo	Number of doors:	5
Model type:	1.0 TSI Comfortline	Vehicle length (cm):	
License plate:	G665ZZ	Vehicle width (cm):	
Report code:	6933	Vehicle height (cm):	
Chassis number:	WVWZZZAWZLU046933	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	13/01/2020	Power(kw):	70
First NL reg.:	13/01/2020	Transmission	Manual
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears	5
Weight (kg)(kg):	1155	Displacement(cc):	999
Empty weight(kg):	1055	Number of cylinders:	3
Wheelbase (cm)(cm):	255	Fuel type:	Petrol
Top speed (km/h):	187	Fuel tank capacity:	
Cons. in the city (l/100 km):	5.7	EU category:	Euro 6
Cons. outside the city (l/100 km):	4	Energy label:	B
Average consumption (l/100 km):	4.6	NL Tax rate %:	
Acceleration (s):	10.8	CO2 (g/km):	105
Cargo space (l):	1155	Nb. of Axles:	2
Perm. max weight (kg):	1610	APK date:	13/01/2026

opties

<input checked="" type="checkbox"/> Daytime running lights	<input checked="" type="checkbox"/> Halogen headlights	<input checked="" type="checkbox"/> Cruise control (adaptive)
<input checked="" type="checkbox"/> Licht Sensor	<input checked="" type="checkbox"/> Exterior mirrors in car body color	<input checked="" type="checkbox"/> Cruise control
<input checked="" type="checkbox"/> bots waarschuwing systeem	<input checked="" type="checkbox"/> Rear wiper	<input checked="" type="checkbox"/> Airconditioning
<input checked="" type="checkbox"/> Anti-lock braking system	<input checked="" type="checkbox"/> Rear parking sensors	<input checked="" type="checkbox"/> Climate control
<input checked="" type="checkbox"/> ABS	<input checked="" type="checkbox"/> Front parking sensors	<input checked="" type="checkbox"/> Climate control (analog)
<input checked="" type="checkbox"/> Airbag(s)	<input checked="" type="checkbox"/> Rear-seat folding (equal parts)	<input checked="" type="checkbox"/> Large screen navigation
<input checked="" type="checkbox"/> Audio	<input checked="" type="checkbox"/> Rear-seat folding (unequal parts)	<input checked="" type="checkbox"/> Electrically operated rear windows
<input checked="" type="checkbox"/> Central locking system	<input checked="" type="checkbox"/> Luggage cover	<input checked="" type="checkbox"/> Electrically operated front windows
<input checked="" type="checkbox"/> Fog lamps	<input checked="" type="checkbox"/> USB connection	<input checked="" type="checkbox"/> Electrically adjustable mirrors
<input checked="" type="checkbox"/> Start/stop system	<input checked="" type="checkbox"/> Bluetooth streaming	<input checked="" type="checkbox"/> Central armrest front
<input checked="" type="checkbox"/> Power steering	<input checked="" type="checkbox"/> DAB+	<input checked="" type="checkbox"/> Audio control on the steering wheel
<input checked="" type="checkbox"/> Front seats adjustable in height	<input checked="" type="checkbox"/> Radio/CD player	<input checked="" type="checkbox"/> Leather steering wheel
<input checked="" type="checkbox"/> Multifunctional steering wheel	<input checked="" type="checkbox"/> Bluetooth car kit	<input checked="" type="checkbox"/> Pedestrian safety system
<input checked="" type="checkbox"/> Remote central locking	<input checked="" type="checkbox"/> Radio	
<input checked="" type="checkbox"/> Metallic finish	<input checked="" type="checkbox"/> WiFi	

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Winter	Steel	185/65 R15	Continental	5
Tire left rear	Winter	Steel	185/65 R15	Continental	6
Tire right front	Winter	Steel	185/65 R15	Continental	5
Tire right rear	Winter	Steel	185/65 R15	Continental	6

Additional information

No. of keys:	1	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black		Maintenance booklet:	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5		Stamp date:	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5		Last turn mileage(km):	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- ☒ Clean inside (Interior is clean)
- ☐ Clean outside

🔧 Damages

⊕ Not acceptable



Front bumper - Scratch



Rear left screen - Restyle dent



Rear bumper - Scratch



Rear right screen - Restyle dent





Bonnet - Bird droppings

🔧 Damages

⊕ Acceptable

⚙️ Extra options







AUTOF[▲]CTOR
SOFTWARE FOR AUTOMOTIVE