

Inspected by: Rob Datema



Brand:	Opel	Mileage(km):	180907
Model:	Karl	Number of doors:	5
Model type:	1.0 ecoFLEX Edition	Vehicle length (cm):	
License plate:	RV636P	Vehicle width (cm):	
Report code:	0992	Vehicle height (cm):	
Chassis number:	W0VDD6E76JC430992	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	15/02/2018	Power(kw):	55
First NL reg.:	15/02/2018	Transmission	Manual
Color:	White Metallic	Number of gears	5
Weight (kg)(kg):	939	Displacement(cc):	999
Empty weight(kg):	839	Number of cylinders:	3
Wheelbase (cm)(cm):	239	Fuel type:	Petrol
Top speed (km/h):	170	Fuel tank capacity:	
Cons. in the city (I/100 km):	5.1	EU category:	Euro 6
Cons. outside the city (I/100 km):	3.7	Energy label:	В
Avarage consumption (I/100 km):	4.1	NL Tax Rate %:	
Acceleration (s):	13.9	CO2 (q/km):	94
Cargo space (I):	939	Nb. of Axles:	2
Perm. max weight (kg):	1353	APK date:	22/02/2026

opties

- ABS
- Airbag(s)
- Power steering
- Multifunctional steering wheel
- Remote central locking
- Halogen headlights

- Exterior mirrors in car body color

- Exterior mirrors in Rear wiper
 Luggage cover
 USB connection
 Radio/CD/MP3 pl
 Bluetooth car kit Radio/CD/MP3 player

- ✓ Radio
 ✓ Cruise control
 ✓ Airconditioning
 ✓ Electrically operated front windows
 ✓ Electrically adjustable mirrors
 ✓ Audio control on the steering wheel

🗱 Tires

Tire	Tire	Wheel	Tire size:	Tire brand:	Tire profile depth (mm):
position:	type:	type:			
Tire left front	Summer	Steel	165/65 R14	Continental	5
Tire left rear	Summer	Steel	165/65 R14	Michelin	4
Tire right front	Summer	Steel	165/65 R14	Continental	5
Tire right rear	Summer	Steel	165/65 R14	Continental	4

Additional information

No. of keys:	1 Luxury key	Instruction booklet		Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	Odorless (Rook)
Upholstery:	Stof			Clean inside (Professional Cleaning)
No. of seats:	5	Stamp date:	16/02/2024	✓ Display ok
No. of headrests:	5	Last turn mileage(km):	163024	▼ Vehicle special usage (None)

A Cleaning

- Clean inside (Professional Cleaning)
- Clean outside

Damages


Not acceptable







Left sill - Dent



Rear bumper - Scratch



Front bumper - Paint repair



Versnellingsbaklagers Hoorbaar

Damages

♥ Extra options



















































