



Brand:	Land Rover	Mileage(km):	92182
Model:	Range Rover Sport	Number of doors:	5
Model type:	3.0 TDV6 HSE Dynamic Luchtvering Winter	Vehicle length (cm):	
	Pack	Vehicle width (cm):	
License plate:	KX356R	Vehicle height (cm):	
Report code:	2359	Vehicle body type:	
Chassis number:	SALWA2KF1FA522359	Traction:	Front+Rear
Type of vehicle:	Luxury	Power(kw):	190
First int. reg.:	11/09/2015	Transmission	Automatic
First NL rea.:	23/12/2016	Transmission	Automatic
		Number of gears	8
Color:	Brown Metallic	Displacement(cc):	2993
Weight (kg)(kg):	2183	Number of cylinders:	6
Empty weight(kg):	2083	Fuel type:	Diesel
Wheelbase (cm)(cm):	292	Fuel tank capacity:	
Top speed (km/h):	210	EU category:	Euro 5
Cons. in the city (I/100 km):	7.8	Frank lakels	-
Cons. outside the city (I/100 km):	6.3	Energy label:	D
		NL Tax Rate %:	25
Avarage consumption (I/100 km):	6.9	CO2 (g/km):	182
Acceleration (s):	7.6	Nb. of Axles:	2
Cargo space (I):	2183	APK date:	02/10/2025
Perm. max weight (kg):	3000		02,10,2020

Inspected by: Rob Datema

🗱 opties

7.100				
Alloy wheels		Exterior mirrors with step light	~	Climate control (analog)
Leather upholstery	~	Privacy glass	~	Climate control (digital)
Air suspension		Rain sensor		Climate control (L/R separated)
Daytime running lights	=	Rear wiper		Large screen navigation
Licht Sensor	~	Rear view camera	~	Keyless entry
Towing hook	=	Rear parking sensors	~	Keyless entry/start/stop
Anti-lock braking system	=	Front parking sensors	~	Keyless start/stop
ABS	=	Towbar with detachable ball	~	Electrically operated rear windows
Airbag(s)	\sim	Rear-seat folding (equal parts)	~	Electrically operated front windows
Audio	Image: Second	Rear-seat folding (unequal parts)	~	Electrically heated windscreen
Central locking system	Image: Second	Luggage cover	~	Electrically folding mirrors
Fog lamps		Trunk opens electrically		Electrically adjustable mirrors
Start/stop system	Image: Second	Aux connection	~	Electrically adjustable driver's seat
Power steering	Image: A start and a start	USB connection		Electrically adjustable passenger seat
Front seats adjustable in height		Bluetooth streaming		Electrically heated driver's seat
Multifunctional steering wheel	Image: A start and a start	CD changer		Electrically heated passenger seat
Remote central locking	Image: A start and a start	Radio/CD player		Central armrest front
Sports package (exterior)	Image: A start and a start	Radio/CD/MP3 player		Adjustable lumbar support driver's seat
Metallic finish	Image: A start and a start	Bluetooth car kit		Adjustable lumbar support passenger seat
Xenon headlights	Image: A start and a start	Radio		Audio control on the steering wheel
Xenon headlights (adaptive)		Cruise control	\checkmark	Electrically adjustable steering wheel
Headlight washers		Airconditioning		Leather steering wheel
LED rear lights	Image: A start and a start	Airconditioning in the back	~	Switch flippers
Exterior mirrors in car body color	~	Climate control		Heated steering wheel
	Alloy wheels Leather upholstery Air suspension Daytime running lights Licht Sensor Towing hook Anti-lock braking system ABS Airbag(s) Audio Central locking system Fog lamps Start/stop system Power steering Front seats adjustable in height Multifunctional steering wheel Remote central locking Sports package (exterior) Metallic finish Xenon headlights Xenon headlights Xenon headlights Xenon headlights Addight washers LED rear lights	Alloy wheels Y Leather upholstery Y Air suspension Y Daytime running lights Y Licht Sensor Y Towing hook Y Anti-lock braking system Y ABS Y Airbag(s) Y Audio Y Central locking system Y Fog lamps Y Start/stop system Y Power steering Y Front seats adjustable in height Y Multifunctional steering wheel Y Remote central locking Y Sports package (exterior) Y Metallic finish Y Xenon headlights Y Xenon headlights Y LED rear lights Y	Alloy wheelsExterior mirrors with step lightLeather upholsteryPrivacy glassAir suspensionRain sensorDaytime running lightsRear wiperLicht SensorRear view cameraTowing hookRear parking sensorsAnti-lock braking systemFront parking sensorsABSTowbar with detachable ballAirbag(s)Rear-seat folding (equal parts)AudioRear-seat folding (unequal parts)Central locking systemLuggage coverFog lampsTrunk opens electricallyStart/stop systemAux connectionPower steeringUSB connectionFront seats adjustable in heightBluetooth streamingMultifunctional steering wheelCD changerRemote central lockingRadio/CD /MP3 playerSports package (exterior)Radio/CD playerSports package (exterior)Radio/CD mayerMetallic finishBluetooth car kitXenon headlightsRadioKenn headlightsAirconditioningLED rear lightsAirconditioning in the back	Alloy wheelsImage: Exterior mirrors with step lightLeather upholsteryPrivacy glassAir suspensionRain sensorDaytime running lightsRear wiperLicht SensorRear wiperTowing hookRear parking sensorsAnti-lock braking systemFront parking sensorsAltibag(s)Rear-seat folding (equal parts)AudioRear-seat folding (unequal parts)Central locking systemLuggage coverFog lampsTrunk opens electricallyStart/stop systemAux connectionPower steeringUSB connectionFront seats adjustable in heightBluetooth streamingMultifunctional steering wheelCD changerReating (20 CD changerRadio/CD /MP3 playerSports package (exterior)Radio/CD /MP3 playerMetallic finishBluetooth car kitXenon headlights (adaptive)Cruise controlHeadlight washersAirconditioningLED rear lightsAirconditioning in the back

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	All weather	Alloy	275/45 R21	Vredestein	6
Tire left rear	All weather	Alloy	275/45 R21	Vredestein	5
Tire right front	All weather	Alloy	275/45 R21	Vredestein	6
Tire right rear	All weather	Alloy	275/45 R21	Vredestein	5

Additional information No. of keys: 2 Luxury key Instruction booklet Airco works Interior color: Miscellaneous Maintenance booklet: Odorless Upholstery: Leder Clean inside (Interior is clean)

No. of seats:	5	Stamp date:	Display ok
No. of headrests:	5	Last turn mileage(km):	Vehicle special usage (None)
▲ Cleaning			
Clean inside (Interior is	clean)		
Clean outside			
🗲 Damages			Not acceptable
9-7/1/			



56-P

Tailgate/ lid - Scratch





Rear left door - Dent



Bonnet - Bird droppings



Rear right rim - Scratch







































































AUTOF CTOR SOFTWARE FOR AUTOMOTIVE