



Brand:	Renault	Mileage(km):	79449
Model:	Clio	Number of doors:	5
Model type:	0.9 TCe Zen Navi Airco	Vehicle length (cm):	
License plate:	SP546H	Vehicle width (cm):	
Report code:	5566	Vehicle height (cm):	
Chassis number:	VF15R240A60895566	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	23/05/2018	Power(kw):	66
First NL reg.:	23/05/2018	Transmission	Manual
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears	5
Weight (kg)(kg):	1157	Displacement(cc):	898
Empty weight(kg):	1057	Number of cylinders:	3
Wheelbase (cm)(cm):	259	Fuel type:	Petrol
Top speed (km/h):	180	Fuel tank capacity:	
Cons. in the city (l/100 km):	5.1	EU category:	Euro 6
Cons. outside the city (l/100 km):	3.7	Energy label:	B
Average consumption (l/100 km):	4.2	NL Tax Rate %:	
Acceleration (s):	13.1	CO2 (g/km):	94
Cargo space (l):	1157	Nb. of Axles:	2
Perm. max weight (kg):	1621	APK date:	23/05/2026

opties

- | | | |
|--|--|---|
| <input checked="" type="checkbox"/> Daytime running lights | <input checked="" type="checkbox"/> Halogen headlights | <input checked="" type="checkbox"/> Radio |
| <input checked="" type="checkbox"/> Anti-lock braking system | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Cruise control |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Airconditioning |
| <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> Rear-seat folding (equal parts) | <input checked="" type="checkbox"/> Climate control |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> Rear-seat folding (unequal parts) | <input checked="" type="checkbox"/> Climate control (analog) |
| <input checked="" type="checkbox"/> Central locking system | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Large screen navigation |
| <input checked="" type="checkbox"/> Start/stop system | <input checked="" type="checkbox"/> Aux connection | <input checked="" type="checkbox"/> Keyless entry |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> USB connection | <input checked="" type="checkbox"/> Keyless entry/start/stop |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> Bluetooth streaming | <input checked="" type="checkbox"/> Keyless start/stop |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> DAB+ | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> Radio/CD/MP3 player | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Metallic finish | <input checked="" type="checkbox"/> Bluetooth car kit | <input checked="" type="checkbox"/> Leather steering wheel |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	All weather	Steel	195/55 R16	Michelin	5
Tire left rear	All weather	Steel	195/55 R16	Goodyear	7
Tire right front	All weather	Steel	195/55 R16	Michelin	5
Tire right rear	All weather	Steel	195/55 R16	Goodyear	7

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	<input type="checkbox"/> Odorless (Rokersgeur)
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	11/09/2015	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	33912	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- ☒ Clean inside (Interior is clean)
- ☒ Clean outside (Cleaning)

Damages

⊕ Not acceptable



Front bumper - Scratch



Bonnet - Ontzet



Front left door - Dent



Tailgate/ lid - Scratch



Rear bumper - Scratch



Brandgat passagierstoel

🔧 Damages

⊕ Acceptable

⚙️ Extra options





