



Brand:	Jeep	Mileage(km):	73552
Model:	Compass	Number of doors:	5
Model type:	1.4 MultiAir Night Eagle Clima Navi Camera Trekhaak	Vehicle length (cm):	
License plate:	XH290V	Vehicle width (cm):	
Report code:	4566	Vehicle height (cm):	
Chassis number:	3C4NJC8H3JT404566	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	12/01/2019	Power(kw):	103
First NL reg.:	12/01/2019	Transmission	Manual
Color:	Grey <input checked="" type="checkbox"/> Metallic	Number of gears	6
Weight (kg)(kg):	1515	Displacement(cc):	1368
Empty weight(kg):	1415	Number of cylinders:	4
Wheelbase (cm)(cm):	264	Fuel type:	Petrol
Top speed (km/h):	195	Fuel tank capacity:	
Cons. in the city (l/100 km):	7.8	EU category:	Euro 6
Cons. outside the city (l/100 km):	5.2	Energy label:	E
Average consumption (l/100 km):	6.2	NL Tax Rate %:	
Acceleration (s):	9.8	CO2 (g/km):	143
Cargo space (l):	1515	Nb. of Axles:	2
Perm. max weight (kg):	1916	APK date:	10/11/2026

opties

- | | | |
|--|--|---|
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Halogen headlights | <input checked="" type="checkbox"/> Large screen navigation |
| <input checked="" type="checkbox"/> Licht Sensor | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Keyless entry |
| <input checked="" type="checkbox"/> Towing hook | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Keyless entry/start/stop |
| <input checked="" type="checkbox"/> bots waarschuwing systeem | <input checked="" type="checkbox"/> Rear view camera | <input checked="" type="checkbox"/> Electrically operated rear windows |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Electrically folding mirrors |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> USB connection | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Fog lamps | <input checked="" type="checkbox"/> Bluetooth streaming | <input checked="" type="checkbox"/> Central armrest front |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> DAB+ | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> Bluetooth car kit | <input checked="" type="checkbox"/> Leather steering wheel |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> Radio | <input checked="" type="checkbox"/> Lane assistance |
| <input checked="" type="checkbox"/> Roof rail (black) | <input checked="" type="checkbox"/> Cruise control | |
| <input checked="" type="checkbox"/> Metallic finish | <input checked="" type="checkbox"/> Climate control | |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	All weather	Alloy	225/55 R18	Michelin	4
Tire left rear	All weather	Alloy	225/55 R18	Michelin	5
Tire right front	All weather	Alloy	225/55 R18	Michelin	5
Tire right rear	All weather	Alloy	225/55 R18	Michelin	5

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Half stof/leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:		<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	68602	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning


- ☒ Clean inside (Interior is clean)
- ☒ Clean outside (Polishing)

Damages

⊕ Not acceptable



Bonnet - Restyle dent



Rear bumper - Scratch



Left C- column - Restyle dent



Roof - Restyle dent



Rear right door - Dent



Right C- column - Restyle dent



Front bumper - Scratch

Damages

⊕ Acceptable

Extra options

