



| | | | |
|---|--|-----------------------------|------------|
| Brand: | Renault | Mileage(km): | 180089 |
| Model: | Clio | Number of doors: | 5 |
| Model type: | 1.0 TCe Zen LED | Vehicle length (cm): | |
| License plate: | J793DS | Vehicle width (cm): | |
| Report code: | 9224 | Vehicle height (cm): | |
| Chassis number: | VF1RJA00865549224 | Vehicle body type: | |
| Type of vehicle: | Luxury | Traction: | Front |
| First int. reg.: | 10/07/2020 | Power(kw): | 74 |
| First NL reg.: | 10/07/2020 | Transmission | Manual |
| Color: | Grey <input checked="" type="checkbox"/> Metallic | Number of gears | 5 |
| Weight (kg)(kg): | 1165 | Displacement(cc): | 999 |
| Empty weight(kg): | 1065 | Number of cylinders: | 3 |
| Wheelbase (cm)(cm): | 258 | Fuel type: | Petrol |
| Top speed (km/h): | 187 | Fuel tank capacity: | |
| Cons. in the city (l/100 km): | 5.5 | EU category: | Euro 6 |
| Cons. outside the city (l/100 km): | 3.6 | Energy label: | B |
| Average consumption (l/100 km): | 4.3 | NL Tax Rate %: | |
| Acceleration (s): | 11.8 | CO2 (g/km): | 99 |
| Cargo space (l): | 1165 | Nb. of Axles: | 2 |
| Perm. max weight (kg): | 1603 | APK date: | 08/05/2026 |

opties

- | | | |
|--|--|---|
| <input checked="" type="checkbox"/> Daytime running lights | <input checked="" type="checkbox"/> LED rear lights | <input checked="" type="checkbox"/> Airconditioning |
| <input checked="" type="checkbox"/> Licht Sensor | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Climate control |
| <input checked="" type="checkbox"/> Towing hook | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Climate control (analog) |
| <input checked="" type="checkbox"/> Anti-lock braking system | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Climate control (digital) |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Towbar with fixed ball | <input checked="" type="checkbox"/> Large screen navigation |
| <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> Rear-seat folding (equal parts) | <input checked="" type="checkbox"/> Keyless entry |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> Rear-seat folding (unequal parts) | <input checked="" type="checkbox"/> Keyless entry/start/stop |
| <input checked="" type="checkbox"/> Central locking system | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Keyless start/stop |
| <input checked="" type="checkbox"/> Start/stop system | <input checked="" type="checkbox"/> Aux connection | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> USB connection | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> Bluetooth streaming | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> DAB+ | <input checked="" type="checkbox"/> Leather steering wheel |
| <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> Bluetooth car kit | <input checked="" type="checkbox"/> Lane assistance |
| <input checked="" type="checkbox"/> Metallic finish | <input checked="" type="checkbox"/> Radio | <input checked="" type="checkbox"/> Pedestrian safety system |
| <input checked="" type="checkbox"/> LED headlights | <input checked="" type="checkbox"/> Cruise control | |

Tires

| Tire position: | Tire type: | Wheel type: | Tire size: | Tire brand: | Tire profile depth (mm): |
|------------------|------------|-------------|------------|-------------|--------------------------|
| Tire left front | Winter | Steel | 195/55 R16 | Continental | 8 |
| Tire left rear | Winter | Steel | 195/55 R16 | Michelin | 6 |
| Tire right front | Winter | Steel | 195/55 R16 | Continental | 8 |
| Tire right rear | Winter | Steel | 195/55 R16 | Continental | 6 |

Additional information

| | | | | |
|--------------------------|-------|-------------------------------------|--|--|
| No. of keys: | 2 | <input type="checkbox"/> Luxury key | <input type="checkbox"/> Instruction booklet | <input checked="" type="checkbox"/> Airco works |
| Interior color: | Black | Maintenance booklet: | (serviceboekje (papier)) | <input checked="" type="checkbox"/> Odorless |
| Upholstery: | Stof | | | <input checked="" type="checkbox"/> Clean inside (Interior is clean) |
| No. of seats: | 5 | Stamp date: | 14/06/2022 | <input checked="" type="checkbox"/> Display ok |
| No. of headrests: | 5 | Last turn mileage(km): | 86132 | <input checked="" type="checkbox"/> Vehicle special usage (None) |

Cleaning


- ☒ Clean inside (Interior is clean)
- ☒ Clean outside (Cleaning)

🔧 Damages

⊗ Not acceptable



Front bumper - Scratch




Rear left door - Restyle dent



Front left door - Rust formation



Rear bumper - Scratch



Rear right screen - Restyle dent



Rear right door - Scratch



Right B- column - Restyle dent



Roof - Hail damage



Condensor lek

🔧 Damages

⊕ Acceptable

⚙️ Extra options



