



Brand:	Skoda	Mileage(km):	138225
Model:	Octavia Combi	Number of doors:	5
Model type:	1.0 Aut. e-TSI Business Edition Plus Org.NL Winterpakket	Vehicle length (cm):	
License plate:	K106GF	Vehicle width (cm):	
Report code:	2436	Vehicle height (cm):	
Chassis number:	TMBJP7NX2MY072436	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	15/12/2020	Power(kw):	81
First NL reg.:	15/12/2020	Transmission	Automatic
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears	7
Weight (kg)(kg):	1353	Displacement(cc):	999
Empty weight(kg):	1253	Number of cylinders:	3
Wheelbase (cm)(cm):	269	Fuel type:	Petrol
Top speed (km/h):	201	Fuel tank capacity:	
Cons. in the city (l/100 km):	5.1	EU category:	Euro 6
Cons. outside the city (l/100 km):	3.9	Energy label:	A
Average consumption (l/100 km):	4.4	NL Tax Rate %:	
Acceleration (s):	10.6	CO2 (g/km):	100
Cargo space (l):	1353	Nb. of Axles:	2
Perm. max weight (kg):	1860	APK date:	31/12/2026

opties

<input checked="" type="checkbox"/> Alloy wheels	<input checked="" type="checkbox"/> Exterior mirrors in car body color	<input checked="" type="checkbox"/> Keyless entry/start/stop
<input checked="" type="checkbox"/> Digital dashboard	<input checked="" type="checkbox"/> Privacy glass	<input checked="" type="checkbox"/> Keyless start/stop
<input checked="" type="checkbox"/> Daytime running lights	<input checked="" type="checkbox"/> Rain sensor	<input checked="" type="checkbox"/> Electrically operated rear windows
<input checked="" type="checkbox"/> Licht Sensor	<input checked="" type="checkbox"/> Rear wiper	<input checked="" type="checkbox"/> Electrically operated front windows
<input checked="" type="checkbox"/> Towing hook	<input checked="" type="checkbox"/> Rear parking sensors	<input checked="" type="checkbox"/> Electrically folding mirrors
<input checked="" type="checkbox"/> bots waarschuwing systeem	<input checked="" type="checkbox"/> Front parking sensors	<input checked="" type="checkbox"/> Electrically adjustable mirrors
<input checked="" type="checkbox"/> Anti-lock braking system	<input checked="" type="checkbox"/> Towbar with detachable ball	<input checked="" type="checkbox"/> Electrically adjustable driver's seat
<input checked="" type="checkbox"/> ABS	<input checked="" type="checkbox"/> Luggage cover	<input checked="" type="checkbox"/> Electrically adjustable driver's seat (including memory)
<input checked="" type="checkbox"/> Airbag(s)	<input checked="" type="checkbox"/> Trunk opens electrically	<input checked="" type="checkbox"/> Electrically heated driver's seat
<input checked="" type="checkbox"/> Audio	<input checked="" type="checkbox"/> USB connection	<input checked="" type="checkbox"/> Electrically heated passenger seat
<input checked="" type="checkbox"/> Central locking system	<input checked="" type="checkbox"/> DAB+	<input checked="" type="checkbox"/> Central armrest front
<input checked="" type="checkbox"/> Fog lamps	<input checked="" type="checkbox"/> Bluetooth car kit	<input checked="" type="checkbox"/> Adjustable lumbar support driver's seat
<input checked="" type="checkbox"/> Start/stop system	<input checked="" type="checkbox"/> WiFi	<input checked="" type="checkbox"/> Adjustable lumbar support passenger seat
<input checked="" type="checkbox"/> Power steering	<input checked="" type="checkbox"/> Cruise control (adaptive)	<input checked="" type="checkbox"/> Audio control on the steering wheel
<input checked="" type="checkbox"/> Front seats adjustable in height	<input checked="" type="checkbox"/> Cruise control	<input checked="" type="checkbox"/> Leather steering wheel
<input checked="" type="checkbox"/> Multifunctional steering wheel	<input checked="" type="checkbox"/> Airconditioning	<input checked="" type="checkbox"/> Switch flippers
<input checked="" type="checkbox"/> Remote central locking	<input checked="" type="checkbox"/> Airconditioning in the back	<input checked="" type="checkbox"/> Heated steering wheel
<input checked="" type="checkbox"/> Roof rail (silver)	<input checked="" type="checkbox"/> Climate control	<input checked="" type="checkbox"/> Lane assistance
<input checked="" type="checkbox"/> Metallic finish	<input checked="" type="checkbox"/> Climate control (digital)	<input checked="" type="checkbox"/> Pedestrian safety system
<input checked="" type="checkbox"/> LED headlights	<input checked="" type="checkbox"/> Climate control (L/R separated)	<input checked="" type="checkbox"/> Dead angle assistance
<input checked="" type="checkbox"/> Headlight washers	<input checked="" type="checkbox"/> Large screen navigation	
<input checked="" type="checkbox"/> LED rear lights	<input checked="" type="checkbox"/> Keyless entry	

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	225/45 R18	Goodyear	4
Tire left rear	Summer	Alloy	225/45 R18	Goodyear	4
Tire right front	Summer	Alloy	225/45 R18	Goodyear	4
Tire right rear	Summer	Alloy	225/45 R18	Goodyear	4

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	07/08/2024	<input checked="" type="checkbox"/> Display ok

No. of headrests:

5

Last turn mileage(km):

119020

☒ Vehicle special usage (None)

Cleaning

☒ Clean inside (Interior is clean)

☒ Clean outside (Polishing)

Damages

 Not acceptable




Front left rim - Scratch



Front bumper - Scratch



Front bumper - Scratch



Bonnet - Paint repair




Rear left screen - Scratch



Rear bumper - Dent



Rear bumper - Scratch




Rear right door - Scratch



Damages


 Acceptable

Extra options









AUTOF[▲]CTOR
SOFTWARE FOR AUTOMOTIVE