



Brand:	Volkswagen	Mileage(km):	81715
Model:	Polo	Number of doors:	5
Model type:	1.0 MPI Comfortline Org.NL	Vehicle length (cm):	
License plate:	ZV492J	Vehicle width (cm):	
Report code:	1990	Vehicle height (cm):	
Chassis number:	WVWZZZAWZKU081990	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	16/08/2019	Power(kw):	59
First NL req.:	16/08/2019	Transmission	Manual
Color:	White Metallic	Number of gears	5
Weight (kg)(kg):	1125	Displacement(cc):	999
Empty weight(kg):	1025	Number of cylinders:	3
Wheelbase (cm)(cm):	255	Fuel type:	Petrol
Top speed (km/h):	170	Fuel tank capacity:	
Cons. in the city (I/100 km):	6.1	EU category:	Euro 6
Cons. outside the city (I/100 km):	4.1	Energy label:	С
Avarage consumption (I/100 km):	4.8	NL Tax Rate %:	
Acceleration (s):	14.9	CO2 (g/km):	110
Cargo space (I):	1125	Nb. of Axles:	2
Perm. max weight (kg):	1590	APK date:	16/08/2025

opties

Daytime running lights Licht Sensor bots waarschuwing systeem Anti-lock braking system ABS Airbag(s) Audio Central locking system Fog lamps Start/stop system Power steering Front seats adjustable in height Multifunctional steering wheel

_	Demoste e entrel la chine
~	Remote central locking
\sim	Halogen headlights
~	Exterior mirrors in car body color
$\overline{}$	Privacy glass
\checkmark	Rain sensor
\sim	Rear wiper
\checkmark	Rear-seat folding (equal parts)
\checkmark	Rear-seat folding (unequal parts)
\checkmark	Luggage cover
\mathbf{v}	USB connection
	Bluetooth streaming
$\overline{}$	Bluetooth car kit
~	Radio

১১১১১ Airconditioning Climate control Climate control (analog) Large screen navigation Electrically operated rear windows 22222222 Electrically operated front windows Electrically adjustable mirrors Central armrest front

Cruise control

- Audio control on the steering wheel
- Leather steering wheel
- Pedestrian safety system

¢ [*] Tires					
Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Steel	185/65 R15	Goldline	5
Tire left rear	Summer	Steel	185/65 R15	Continental	5
Tire right front	Summer	Steel	185/65 R15	Goldline	5
Tire right rear	Summer	Steel	185/65 R15	Continental	4

▲ Additional information

No. of keys:	2 🗌 Luxury key	Instruction booklet	Airco works
Interior color:	Black	Maintenance booklet:	Odorless
Upholstery:	Stof		Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	Display ok
No. of headrests:	5	Last turn mileage(km):	Vehicle special usage (None)

A Cleaning Clean inside (Interior is clean)

Clean outside (Cleaning)

Inspected by: Maurice Otten

🖋 Damages

Not acceptable



Front bumper - Scratch



Front bumper - Scratch



Front bumper - Break



Bonnet - Scratch





Rear bumper - Scratch



Rear bumper - Scratch



Right tailgate - Break



Rear right screen - Dent



Front left door - Restyle dent



Right B- column - Restyle dent



Roof - Restyle dent



🗲 Damages	
🎕 Extra options	










































































AUTOF CTOR SOFTWARE FOR AUTOMOTIVE