



<b>Brand:</b>	Opel	<b>Mileage(km):</b>	164628
<b>Model:</b>	Astra	<b>Number of doors:</b>	5
<b>Model type:</b>	1.4 Turbo Edition	<b>Vehicle length (cm):</b>	
<b>License plate:</b>	5KRZ85	<b>Vehicle width (cm):</b>	
<b>Report code:</b>	1742	<b>Vehicle height (cm):</b>	
<b>Chassis number:</b>	W0LPD6EU9D1011742	<b>Vehicle body type:</b>	
<b>Type of vehicle:</b>	Luxury	<b>Traction:</b>	Front
<b>First int. reg.:</b>	27/06/2013	<b>Power(kw):</b>	88
<b>First NL reg.:</b>	27/06/2013	<b>Transmission</b>	Manual
<b>Color:</b>	Grey <input checked="" type="checkbox"/> <b>Metallic</b>	<b>Number of gears</b>	6
<b>Weight (kg)(kg):</b>	1393	<b>Displacement(cc):</b>	1364
<b>Empty weight(kg):</b>	1293	<b>Number of cylinders:</b>	4
<b>Wheelbase (cm)(cm):</b>	269	<b>Fuel type:</b>	Petrol
<b>Top speed (km/h):</b>	192	<b>Fuel tank capacity:</b>	
<b>Cons. in the city (l/100 km):</b>	7.1	<b>EU category:</b>	Euro 5
<b>Cons. outside the city (l/100 km):</b>	4.6	<b>Energy label:</b>	A
<b>Average consumption (l/100 km):</b>	5.5	<b>NL Tax Rate %:</b>	25
<b>Acceleration (s):</b>	11	<b>CO2 (g/km):</b>	129
<b>Cargo space (l):</b>	1393	<b>Nb. of Axles:</b>	2
<b>Perm. max weight (kg):</b>	1945	<b>APK date:</b>	06/10/2025

## opties

- |  |  |   |
|--|--|---|
| <input checked="" type="checkbox"/> Alloy wheels                     | <input checked="" type="checkbox"/> Remote central locking             | <input checked="" type="checkbox"/> CD changer                          |
| <input checked="" type="checkbox"/> Daytime running lights           | <input checked="" type="checkbox"/> Metallic finish                    | <input checked="" type="checkbox"/> Radio/CD player                     |
| <input checked="" type="checkbox"/> Licht Sensor                     | <input checked="" type="checkbox"/> Halogen headlights                 | <input checked="" type="checkbox"/> Radio/CD/MP3 player                 |
| <input checked="" type="checkbox"/> Towing hook                      | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Bluetooth car kit                   |
| <input checked="" type="checkbox"/> Anti-lock braking system         | <input checked="" type="checkbox"/> Rain sensor                        | <input checked="" type="checkbox"/> Radio                               |
| <input checked="" type="checkbox"/> ABS                              | <input checked="" type="checkbox"/> Rear wiper                         | <input checked="" type="checkbox"/> Cruise control                      |
| <input checked="" type="checkbox"/> Airbag(s)                        | <input checked="" type="checkbox"/> Rear parking sensors               | <input checked="" type="checkbox"/> Airconditioning                     |
| <input checked="" type="checkbox"/> Audio                            | <input checked="" type="checkbox"/> Towbar with fixed ball             | <input checked="" type="checkbox"/> Climate control                     |
| <input checked="" type="checkbox"/> Central locking system           | <input checked="" type="checkbox"/> Rear-seat folding (equal parts)    | <input checked="" type="checkbox"/> Climate control (analog)            |
| <input checked="" type="checkbox"/> Fog lamps                        | <input checked="" type="checkbox"/> Rear-seat folding (unequal parts)  | <input checked="" type="checkbox"/> Large screen navigation             |
| <input checked="" type="checkbox"/> Start/stop system                | <input checked="" type="checkbox"/> Luggage cover                      | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Power steering                   | <input checked="" type="checkbox"/> Aux connection                     | <input checked="" type="checkbox"/> Electrically adjustable mirrors     |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> USB connection                     | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Multifunctional steering wheel   | <input checked="" type="checkbox"/> Bluetooth streaming                | <input checked="" type="checkbox"/> Leather steering wheel              |

## Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	215/50 R17	Vredestein	4
Tire left rear	Summer	Alloy	215/50 R17	Bridgestone	6
Tire right front	Summer	Alloy	215/50 R17	Vredestein	6
Tire right rear	Summer	Alloy	215/50 R17	Bridgestone	4

## Additional information

<b>No. of keys:</b>	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
<b>Interior color:</b>	Black	<b>Maintenance booklet:</b>	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
<b>Upholstery:</b>	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
<b>No. of seats:</b>	5	<b>Stamp date:</b>	28/03/2018	<input checked="" type="checkbox"/> Display ok
<b>No. of headrests:</b>	5	<b>Last turn mileage(km):</b>	49584	<input checked="" type="checkbox"/> Vehicle special usage (None)

## Cleaning

- ☒ Clean inside (Interior is clean)
- ☒ Clean outside (Polishing)



Front bumper - Scratch



Front bumper - Break



Front bumper - Scratch




Front left rim - Scratch




Front left door - Restyle dent



Rear left door - Paint repair



Rear left rim - Scratch



Rear left screen - Scratch



Rear bumper - Break



Rear bumper - Scratch



Right C- column - Restyle dent



Right B- column - Scratch



Windscreen - Pip



Versnellingsbak Maakt Lawaai - Kleppendeksel Lek



Deuren bestuurderskant

🔧 Damages

🟢 Acceptable

⚙️ Extra options

