



Brand:	Seat	Mileage(km):	149507
Model:	Ibiza	Number of doors:	5
Model type:	1.0 TSI Style Business Intense Org.NL	Vehicle length (cm):	
License plate:	G503GD	Vehicle width (cm):	
Report code:	6025	Vehicle height (cm):	
Chassis number:	VSSZZKJZLR026025	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	23/09/2019	Power(kw):	70
First NL req.:	23/09/2019	Transmission	Manual
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears	5
Weight (kg)(kg):	1134	Displacement(cc):	999
Empty weight(kg):	1034	Number of cylinders:	3
Wheelbase (cm)(cm):	256	Fuel type:	Petrol
Top speed (km/h):	188	Fuel tank capacity:	
Cons. in the city (l/100 km):	5.6	EU category:	Euro 6
Cons. outside the city (l/100 km):	4	Energy label:	B
Average consumption (l/100 km):	4.6	NL Tax Rate %:	
Acceleration (s):	10.9	CO2 (g/km):	104
Cargo space (l):	1134	Nb. of Axles:	2
Perm. max weight (kg):	1560	APK date:	23/09/2025

opties

- | | | |
|--|--|---|
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Metallic finish | <input checked="" type="checkbox"/> Bluetooth car kit |
| <input checked="" type="checkbox"/> Daytime running lights | <input checked="" type="checkbox"/> Halogen headlights | <input checked="" type="checkbox"/> Cruise control |
| <input checked="" type="checkbox"/> Licht Sensor | <input checked="" type="checkbox"/> LED rear lights | <input checked="" type="checkbox"/> Airconditioning |
| <input checked="" type="checkbox"/> bots waarschuwing systeem | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Climate control |
| <input checked="" type="checkbox"/> Anti-lock braking system | <input checked="" type="checkbox"/> Privacy glass | <input checked="" type="checkbox"/> Climate control (digital) |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Rain sensor | <input checked="" type="checkbox"/> Climate control (L/R separated) |
| <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Large screen navigation |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> Rear view camera | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> bots herkenning systeem | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Electrically folding mirrors |
| <input checked="" type="checkbox"/> Central locking system | <input checked="" type="checkbox"/> Front parking sensors | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Fog lamps | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Central armrest front |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> Aux connection | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> iPod connection | <input checked="" type="checkbox"/> Leather steering wheel |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> USB connection | <input checked="" type="checkbox"/> Pedestrian safety system |
| <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> Radio/CD player | |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Winter	Alloy	185/65 R15	Hankook	7
Tire left rear	Winter	Alloy	185/65 R15	Vredestein	5
Tire right front	Winter	Alloy	185/65 R15	Hankook	7
Tire right rear	Winter	Alloy	185/65 R15	Michelin	6

Additional information

No. of keys:	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof		<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- ☒ Clean inside (Interior is clean)
- ☐ Clean outside

🔧 Damages

⊕ Not acceptable



Front bumper - Scratch



Front bumper - Scratch



Rear bumper - Scratch



Rear bumper - Dent



Rear right screen - Restyle dent



Rear right door - Scratch



Front left screen - Scratch

🔧 Damages

⊕ Acceptable

⚙️ Extra options





