

#### Inspected by: Rob Datema



Brand:	Fiat	Mileage(km):	148128
Model:	500L	Number of doors:	5
Model type:	0.9 TwinAir Lounge   Navi   Clima   Trekhaak	Vehicle length (cm):	
	Cruise	Vehicle width (cm):	
License plate:	JJ200L	Vehicle height (cm):	
Report code:	1606	Vehicle body type:	
Chassis number:	ZFA19900005241606	Traction:	Front
Type of vehicle:	Luxury	Power(kw):	77
First int. reg.:	31/03/2016	Transmission	Manual
First NL reg.:	31/03/2016	Number of gears	6
Color:	Grey Metallic	Displacement(cc):	875
Weight (kg)(kg):	1365	Number of cylinders:	2
Empty weight(kg):	1265	Fuel type:	Petrol
Wheelbase (cm)(cm):	261	Fuel tank capacity:	
Top speed (km/h):	180	EU category:	Euro 6
Cons. in the city (I/100 km):	5.7	Energy label:	В
Cons. outside the city (I/100 km):	4.3	NL Tax Rate %:	25
Avarage consumption (I/100 km):	4.8	CO2 (a/km):	112
Acceleration (s):	12.5	Nb. of Axles:	2
Cargo space (i):	1365	APK date:	31/03/2026
Perm. max weight (kg):	1805		31,00,2320

### opties 🚓

Alloy wheels

Daytime running lights

Licht Sensor Towing hook

Anti-lock braking system

ABS

Airbag(s)

Audio

Central locking system

Fog lamps

Start/stop system

Power steering

Front seats adjustable in height

Multifunctional steering wheel

Remote central locking

Metallic finish

Halogen headlights
Exterior mirrors in ca
Privacy glass
Range

Exterior mirrors in car body color

1 Rear wiper

Rear parking sensors

Towbar with fixed ball

 $\overline{\mathbf{v}}$ Rear-seat folding (equal parts)

Rear-seat folding (unequal parts)

Luggage cover

Aux connection

22222 USB connection

Bluetooth streaming

Radio/CD player Radio/CD/MP3 player Bluetooth car kit

Radio

Cruise control

Airconditioning

Climate control

Climate control (analog)

Climate control (digital)

Climate control (L/R separated)

Large screen navigation

Electrically operated rear windows

Electrically operated front windows

Electrically adjustable mirrors

Audio control on the steering wheel

Leather steering wheel

## **♥** Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	All weather	Alloy	205/55 R16	Vredestein	5
Tire left rear	All weather	Alloy	205/55 R16	Vredestein	6
Tire right front	All weather	Alloy	205/55 R16	Vredestein	5
Tire right rear	All weather	Alloy	205/55 R16	Vredestein	6

## Additional information

	No. of keys:	2 Luxury key	☐ Instruction booklet	(serviceboekje (papier))	Airco works
	Interior color:	Black	Maintenance booklet:		Odorless
	Upholstery:	Half stof/leder	r		Clean inside (Interior is clean)
	No. of seats:	5	Stamp date:	15/02/2022	<b>☑</b> Display ok
	No. of headrests:	5	Last turn mileage(km):	85224	Vehicle special usage (None)

### A Cleaning

Clean inside (Interior is clean)

Damages

## Not acceptable



Front left rim - Scratch



Front bumper - Scratch



Windscreen - Pip



Rear bumper - Scratch



Tailgate/ lid - Scratch



Rear bumper - Scratch



Roof - Bird droppings



Rear right rim - Scratch



Voertuig rondom - Paint repair



Right C- column - Restyle dent



Bestuurderstoel beschadigd












































































# AUTOF CTOR