

Inspected by: Rob Datema



| Brand: | Seat | Mileage(km): | 191790 | | |
|------------------------------------|---------------------------------|----------------------|------------|--|--|
| Model: | Leon | Number of doors: | 5 | | |
| Model type: | 1.0 TSI Style Launch Edition | Vehicle length (cm): | | | |
| License plate: | J002LG | Vehicle width (cm): | | | |
| Report code: | 3199 | Vehicle height (cm): | | | |
| Chassis number: | VSSZZZKLZMR003199 | Vehicle body type: | | | |
| Type of vehicle: | Luxury | Traction: | Front | | |
| First int. reg.: | 04/09/2020 | Power(kw): | 81 | | |
| First NL req.: | 04/09/2020 | Transmission | Manual | | |
| Color: | White Metallic | Number of gears | 6 | | |
| Weight (kg)(kg): | 1279 | Displacement(cc): | 999 | | |
| Empty weight(kg): | 1179 | Number of cylinders: | 3 | | |
| Wheelbase (cm)(cm): | 269 | Fuel type: | Petrol | | |
| Top speed (km/h): | 197 | Fuel tank capacity: | | | |
| Cons. in the city (I/100 km): | 5.7 | EU category: | Euro 6 | | |
| Cons. outside the city (I/100 km): | 4.1 | Energy label: | В | | |
| Avarage consumption (I/100 km): | 4.7 | NL Tax Rate %: | | | |
| Acceleration (s): | 10.9 | CO2 (q/km): | 107 | | |
| Cargo space (I): | 1279 | Nb. of Axles: | 2 | | |
| Perm. max weight (kg): | 1750 | APK date: | 04/09/2026 | | |

opties 🚓

- Alloy wheels
- Daytime running lights
- Licht Sensor bots waarschuwing systeem
- Anti-lock braking system
- ABS
- Airbag(s)
- Audio
- bots herkenning systeem
- Central locking system
- Fog lamps
- Start/stop system
- Power steering
- Front seats adjustable in height
- Multifunctional steering wheel Remote central locking
- Sports package (exterior)
- LED headlights

- LED rear lights
 Exterior mirrors
 Privacy glass
 Rain sensor
 - Exterior mirrors in car body color

- Rear wiper ~
- Rear view camera ${f \checkmark}$
- **>** Rear parking sensors
- Front parking sensors
- Luggage cover USB connection
- DAB+
- ~ Bluetooth car kit
- Radio
- WiFi
- 12121 Cruise control (adaptive)
- Cruise control
- Airconditioning
- Airconditioning in the back

- Climate control
- Climate control (digital)
- Climate control (L/R separated)
 - Large screen navigation
- Keyless entry
- Keyless entry/start/stop
- Keyless start/stop
- Electrically operated rear windows
- Electrically operated front windows
- Electrically adjustable mirrors
- Central armrest front
- Adjustable lumbar support driver's seat
- Adjustable lumbar support passenger seat
- Audio control on the steering wheel Leather steering wheel
- Lane assistance
- Pedestrian safety system

♥ Tires

| Tire | Tire | Wheel | Tire size: | Tire brand: | Tire profile depth (mm): |
|------------------|-------------|-------|------------|-------------|--------------------------|
| position: | type: | type: | | | |
| Tire left front | All weather | Alloy | 225/45 R17 | Vredestein | 2 |
| Tire left rear | All weather | Alloy | 225/45 R17 | Hankook | 5 |
| Tire right front | All weather | Alloy | 225/45 R17 | Vredestein | 2 |
| Tire right rear | All weather | Allov | 225/45 R17 | Hankook | 5 |

Additional information

| | No. of keys: | 2 Luxury key | ☐ Instruction booklet | (serviceboekje (papier)) | Airco works |
|--|-------------------|-----------------|------------------------|--------------------------|----------------------------------|
| | Interior color: | Black | Maintenance booklet: | | Odorless |
| | Upholstery: | Half stof/leder | | | Clean inside (Interior is clean) |
| | No. of seats: | 5 | Stamp date: | 07/03/2022 | ☑ Display ok |
| | No. of headrests: | 5 | Last turn mileage(km): | 58288 | ▼ Vehicle special usage (None) |

Damages





Front right rim - Scratch



Front bumper - Scratch



Front left door - Restyle dent



Rear left door - Scratch



Rear bumper - Break



Front left screen - Scratch

Damages

Acceptable

☼ Extra options



































































AUTOF CTOR