

Inspected by: Mik Kieft



Brand:	Peugeot	Mileage(km):	123032
Model:	108	Number of doors:	5
Model type:	1.0 e-VTi Active	Vehicle length (cm):	
License plate:	G611JN	Vehicle width (cm):	
Report code:	7355	Vehicle height (cm):	
Chassis number:	VF3PSCFB5KR017355	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	11/10/2019	Power(kw):	53
First NL reg.:	11/10/2019	Transmission	Manual
Color:	White Metallic	Number of gears	5
Weight (kg)(kg):	915	Displacement(cc):	998
Empty weight(kg):	815	Number of cylinders:	3
Wheelbase (cm)(cm):	234	Fuel type:	Petrol
Top speed (km/h):	160	Fuel tank capacity:	
Cons. in the city (I/100 km):		EU category:	Euro 6
Cons. outside the city (I/100 km):		Energy label:	В
Avarage consumption (I/100 km): 3.7		NL Tax Rate %:	
Acceleration (s):	12.6	CO2 (q/km):	85
Cargo space (I):	915	Nb. of Axles:	2
Perm. max weight (kg):	1240	APK date:	11/10/2025

opties

- Airbag(s)
- Audio
- Central locking system
- Fog lamps
- Power steering
- Multifunctional steering wheel
- रारारारारार Remote central locking

- Halogen headlights
- Exterior mirrors in car body color
- Privacy glass
- 7777 Rear wiper
 - Rear-seat folding (equal parts)
- Luggage cover
- Aux connection
 USB connection

- Bluetooth car kit
 Airconditioning
 Electrically operat
 Electrically adjust
 Audio control on t
 Leather steering v
- Electrically operated front windows
- Electrically adjustable mirrors
- Audio control on the steering wheel Leather steering wheel

🗱 Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer		165/65 R14	tyfoon	4
Tire left rear	Summer		165/65 R14	tyfoon	4
Tire right front	Summer		165/65 R14	tyfoon	4
Tire right rear	Summer		165/65 R14	tyfoon	4

A Additional information

	No. of keys:	2 Luxury key	Instruction booklet		Airco works
	Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	Odorless
	Upholstery:	Stof			Clean inside (Interior is clean)
	No. of seats:	4	Stamp date:	06/12/2021	✓ Display ok
	No. of headrests:	4	Last turn mileage(km):	30361	Vehicle special usage (None)

A Cleaning

- Clean inside (Interior is clean)
- Clean outside

Damages



Front left door - Dent



Rear bumper - Scratch



Brand gat bestuurders stoel



Brand gat bestuurders stoel



Brand gat bestuurders stoel

Damages

♥ Extra options

















































