



Brand:	Skoda	Mileage(km):	223309
Model:	Fabia Combi	Number of doors:	5
Model type:	1.2 TSI Fresh	Vehicle length (cm):	
License plate:	3KRT24	Vehicle width (cm):	
Report code:	4801	Vehicle height (cm):	
Chassis number:	TMBJM25J9E3014801	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	21/09/2013	Power(kw):	63
First NL reg.:	21/09/2013	Transmission	Manual
Color:	Beige <input checked="" type="checkbox"/> Metallic	Number of gears	5
Weight (kg)(kg):	1136	Displacement(cc):	1197
Empty weight(kg):	1036	Number of cylinders:	4
Wheelbase (cm)(cm):	246	Fuel type:	Petrol
Top speed (km/h):	178	Fuel tank capacity:	
Cons. in the city (l/100 km):	6.6	EU category:	Euro 5
Cons. outside the city (l/100 km):	4.3	Energy label:	B
Average consumption (l/100 km):	5.1	NL Tax Rate %:	25
Acceleration (s):	11.8	CO2 (g/km):	119
Cargo space (l):	1136	Nb. of Axles:	2
Perm. max weight (kg):	1591	APK date:	06/06/2025

opties

- | | | |
|--|--|---|
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Roof rail (black) | <input checked="" type="checkbox"/> Radio/CD player |
| <input checked="" type="checkbox"/> Daytime running lights | <input checked="" type="checkbox"/> Metallic finish | <input checked="" type="checkbox"/> Radio/CD/MP3 player |
| <input checked="" type="checkbox"/> Towing hook | <input checked="" type="checkbox"/> Halogen headlights | <input checked="" type="checkbox"/> Radio |
| <input checked="" type="checkbox"/> Anti-lock braking system | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Cruise control |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Airconditioning |
| <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> Towbar with fixed ball | <input checked="" type="checkbox"/> Climate control |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> Rear-seat folding (equal parts) | <input checked="" type="checkbox"/> Climate control (analog) |
| <input checked="" type="checkbox"/> Central locking system | <input checked="" type="checkbox"/> Rear-seat folding (unequal parts) | <input checked="" type="checkbox"/> Climate control (digital) |
| <input checked="" type="checkbox"/> Fog lamps | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Electrically operated rear windows |
| <input checked="" type="checkbox"/> Start/stop system | <input checked="" type="checkbox"/> Aux connection | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> iPod connection | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> USB connection | <input checked="" type="checkbox"/> Central armrest front |
| <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> CD changer | <input checked="" type="checkbox"/> Leather steering wheel |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	185/60 R15	Continental	4
Tire left rear	Summer	Alloy	185/60 R15	Continental	4
Tire right front	Summer	Alloy	185/60 R15	Continental	7
Tire right rear	Summer	Alloy	185/60 R15	Continental	4

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	17/05/2024	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	195074	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- ☒ Clean inside (Interior is clean)
- ☐ Clean outside

Damages

Ⓢ Not acceptable



Front right rim - Scratch



Front bumper - Scratch



Rear bumper - Scratch



Rear bumper - Scratch





Stuurwiel slijtage

Damages

Ⓢ Acceptable

Extra options







AUTOF[▲]CTOR
SOFTWARE FOR AUTOMOTIVE