



|                                    |  |                      |            |
|------------------------------------|--|----------------------|------------|
| Brand:                             | Opel   | Mileage(km):         | 234384     |
| Model:                             | Astra Sports Tourer                                | Number of doors:     | 5          |
| Model type:                        | 1.6 CDTI Innovation   Schuifdak   Trekhaak   Airco | Vehicle length (cm): |            |
| License plate:                     | KL544N   | Vehicle width (cm):  |            |
| Report code:                       | 7613   | Vehicle height (cm): |            |
| Chassis number:                    | W0LBE8EG8H8007613                                  | Vehicle body type:   |            |
| Type of vehicle:                   | Luxury   | Traction:            | Front      |
| First int. reg.:                   | 12/10/2016   | Power(kw):           | 100        |
| First NL reg.:                     | 12/10/2016   | Transmission         | Manual     |
| Color:                             | White <input type="checkbox"/> Metallic            | Number of gears      | 6          |
| Weight (kg)(kg):                   | 1393   | Displacement(cc):    | 1598       |
| Empty weight(kg):                  | 1293   | Number of cylinders: | 4          |
| Wheelbase (cm)(cm):                | 266  | Fuel type:           | Diesel     |
| Top speed (km/h):                  | 205  | Fuel tank capacity:  |            |
| Cons. in the city (l/100 km):      | 4.7  | EU category:         | Euro 6     |
| Cons. outside the city (l/100 km): | 3.5  | Energy label:        | C          |
| Average consumption (l/100 km):    | 3.9  | NL Tax Rate %:       | 25         |
| Acceleration (s):                  | 10.1   | CO2 (g/km):          | 104        |
| Cargo space (l):                   | 1393   | Nb. of Axles:        | 2          |
| Perm. max weight (kg):             | 1950   | APK date:            | 23/10/2025 |

## opties

|   |  |  |
|---|--|--|
| <input checked="" type="checkbox"/> Alloy wheels                      | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Climate control (analog)                 |
| <input checked="" type="checkbox"/> Daytime running lights            | <input checked="" type="checkbox"/> Privacy glass                      | <input checked="" type="checkbox"/> Climate control (digital)                |
| <input checked="" type="checkbox"/> Licht Sensor                      | <input checked="" type="checkbox"/> Rain sensor                        | <input checked="" type="checkbox"/> Climate control (L/R separated)          |
| <input checked="" type="checkbox"/> Towing hook                       | <input checked="" type="checkbox"/> Rear wiper                         | <input checked="" type="checkbox"/> Large screen navigation                  |
| <input checked="" type="checkbox"/> bots waarschuwing systeem         | <input checked="" type="checkbox"/> Rear view camera                   | <input checked="" type="checkbox"/> Keyless entry                            |
| <input checked="" type="checkbox"/> Anti-lock braking system          | <input checked="" type="checkbox"/> Rear parking sensors               | <input checked="" type="checkbox"/> Keyless entry/start/stop                 |
| <input checked="" type="checkbox"/> ABS                               | <input checked="" type="checkbox"/> Front parking sensors              | <input checked="" type="checkbox"/> Keyless start/stop                       |
| <input checked="" type="checkbox"/> Airbag(s)                         | <input checked="" type="checkbox"/> Towbar with detachable ball        | <input checked="" type="checkbox"/> Electrically operated rear windows       |
| <input checked="" type="checkbox"/> Audio                             | <input checked="" type="checkbox"/> Rear-seat folding (equal parts)    | <input checked="" type="checkbox"/> Electrically operated front windows      |
| <input checked="" type="checkbox"/> Central locking system            | <input checked="" type="checkbox"/> Rear-seat folding (unequal parts)  | <input checked="" type="checkbox"/> Electrically folding mirrors             |
| <input checked="" type="checkbox"/> Fog lamps                         | <input checked="" type="checkbox"/> Luggage cover                      | <input checked="" type="checkbox"/> Electrically adjustable mirrors          |
| <input checked="" type="checkbox"/> Start/stop system                 | <input checked="" type="checkbox"/> Trunk opens electrically           | <input checked="" type="checkbox"/> Central armrest front                    |
| <input checked="" type="checkbox"/> Power steering                    | <input checked="" type="checkbox"/> USB connection                     | <input checked="" type="checkbox"/> Extendable passenger seat                |
| <input checked="" type="checkbox"/> Front seats adjustable in height  | <input checked="" type="checkbox"/> Bluetooth streaming                | <input checked="" type="checkbox"/> Extendable driver's seat                 |
| <input checked="" type="checkbox"/> Multifunctional steering wheel    | <input checked="" type="checkbox"/> DAB+                               | <input checked="" type="checkbox"/> Adjustable lumbar support driver's seat  |
| <input checked="" type="checkbox"/> Remote central locking            | <input checked="" type="checkbox"/> Bluetooth car kit                  | <input checked="" type="checkbox"/> Adjustable lumbar support passenger seat |
| <input checked="" type="checkbox"/> Roof rail (silver)                | <input checked="" type="checkbox"/> Radio                              | <input checked="" type="checkbox"/> Audio control on the steering wheel      |
| <input checked="" type="checkbox"/> Sliding / tilting roof (electric) | <input checked="" type="checkbox"/> WiFi                               | <input checked="" type="checkbox"/> Leather steering wheel                   |
| <input checked="" type="checkbox"/> LED headlights                    | <input checked="" type="checkbox"/> Cruise control (adaptive)          | <input checked="" type="checkbox"/> Lane assistance                          |
| <input checked="" type="checkbox"/> LED headlights (adaptive)         | <input checked="" type="checkbox"/> Cruise control                     | <input checked="" type="checkbox"/> Pedestrian safety system                 |
| <input checked="" type="checkbox"/> Headlight washers                 | <input checked="" type="checkbox"/> Airconditioning                    | <input checked="" type="checkbox"/> Dead angle assistance                    |
| <input checked="" type="checkbox"/> LED rear lights                   | <input checked="" type="checkbox"/> Climate control                    |  |

## Tires

| Tire position:   | Tire type: | Wheel type: | Tire size: | Tire brand: | Tire profile depth (mm): |
|------------------|------------|-------------|------------|-------------|--------------------------|
| Tire left front  | Summer     | Alloy       | 225/40 R18 | Continental | 5                        |
| Tire left rear   | Summer     | Alloy       | 225/40 R18 | Continental | 5                        |
| Tire right front | Summer     | Alloy       | 225/40 R18 | Continental | 5                        |
| Tire right rear  | Summer     | Alloy       | 225/40 R18 | Continental | 5                        |

## Additional information

|                 |                 |                                     |  |  |
|-----------------|-----------------|-------------------------------------|--|--|
| No. of keys:    | 2               | <input type="checkbox"/> Luxury key | <input type="checkbox"/> Instruction booklet | <input checked="" type="checkbox"/> Airco works                      |
| Interior color: | Black           | Maintenance booklet:                | (serviceboekje (papier))                     | <input checked="" type="checkbox"/> Odorless                         |
| Upholstery:     | Half stof/leder |                                     |  | <input checked="" type="checkbox"/> Clean inside (Interior is clean) |
| No. of seats:   | 5               | Stamp date:                         | 03/04/2024                                   | <input checked="" type="checkbox"/> Display ok                       |

No. of headrests:

5

Last turn mileage(km):

217045

☒ Vehicle special usage (None)

## ⚠ Cleaning

☒ Clean inside (Interior is clean)

☒ Clean outside (Cleaning)

## 🔧 Damages

⊕ Not acceptable



Front right rim - Scratch



Front left rim - Scratch



Rear left rim - Scratch



Rear bumper - Scratch



Rear bumper - Scratch



Rear right rim - Scratch



Bestuurderstoel beschadigd

## 🔧 Damages

⊕ Acceptable

## ⚙ Extra options







