



Brand:	Ford	Mileage(km):	200920
Model:	Fiesta	Number of doors:	5
Model type:	1.0 EcoBoost Titanium	Vehicle length (cm):	
License plate:	1TNL25	Vehicle width (cm):	
Report code:	4075	Vehicle height (cm):	
Chassis number:	WF0DXXGAKDES74075	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	29/03/2014	Power(kw):	74
First NL reg.:	29/03/2014	Transmission	Manual
Color:	White <input type="checkbox"/> Metallic	Number of gears	5
Weight (kg)(kg):	1124	Displacement(cc):	998
Empty weight(kg):	1024	Number of cylinders:	3
Wheelbase (cm)(cm):	249	Fuel type:	Petrol
Top speed (km/h):	180	Fuel tank capacity:	
Cons. in the city (l/100 km):	5.3	EU category:	Euro 5
Cons. outside the city (l/100 km):	3.7	Energy label:	A
Average consumption (l/100 km):	4.3	NL Tax Rate %:	25
Acceleration (s):	11.2	CO2 (g/km):	99
Cargo space (l):	1124	Nb. of Axles:	2
Perm. max weight (kg):	1555	APK date:	29/03/2026

opties

- | | | |
|--|---|---|
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Exterior mirrors with step light | <input checked="" type="checkbox"/> Cruise control |
| <input checked="" type="checkbox"/> Daytime running lights | <input checked="" type="checkbox"/> Privacy glass | <input checked="" type="checkbox"/> Airconditioning |
| <input checked="" type="checkbox"/> Anti-lock braking system | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Climate control |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Climate control (analog) |
| <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> Rear-seat folding (equal parts) | <input checked="" type="checkbox"/> Climate control (digital) |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> Rear-seat folding (unequal parts) | <input checked="" type="checkbox"/> Large screen navigation |
| <input checked="" type="checkbox"/> Central locking system | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Fog lamps | <input checked="" type="checkbox"/> Aux connection | <input checked="" type="checkbox"/> Electrically heated windshield |
| <input checked="" type="checkbox"/> Start/stop system | <input checked="" type="checkbox"/> USB connection | <input checked="" type="checkbox"/> Electrically folding mirrors |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> Bluetooth streaming | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> CD changer | <input checked="" type="checkbox"/> Central armrest front |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> Radio/CD player | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> Radio/CD/MP3 player | <input checked="" type="checkbox"/> Leather steering wheel |
| <input checked="" type="checkbox"/> Halogen headlights | <input checked="" type="checkbox"/> Bluetooth car kit | |
| <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Radio | |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	195/50 R15	Hankook	6
Tire left rear	Summer	Alloy	195/50 R15	Hankook	6
Tire right front	Summer	Alloy	195/50 R15	Hankook	6
Tire right rear	Summer	Alloy	195/50 R15	Hankook	6

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	10/03/2025	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	198029	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- ☒ Clean inside (Interior is clean)
- ☒ Clean outside (Cleaning)

Damages

⊕ Not acceptable



Rear left door - Restyle dent



Rear left screen - Paint repair



Rear right screen - Paint repair







Bonnet - Rust formation

Damages

⊕ Acceptable

Extra options







AUTOF▲CTOR
SOFTWARE FOR AUTOMOTIVE