



Brand:	Ssangyong	Mileage(km):	180564
Model:	MUSSO	Number of doors:	
Model type:	2.2 E-XDI Grand Musso SAPPHIRE 4WD AUT /NAV/LEER/XENON	Vehicle length (cm):	
License plate:	081387	Vehicle width (cm):	
Report code:	1387	Vehicle height (cm):	
Chassis number:	KPAX62EESLP081387	Vehicle body type:	
Type of vehicle:	Commercial	Traction:	
First int. reg.:	18/05/2021	Power(kw):	133
First NL reg.:		Transmission	Automatic
Color:	Blue <input checked="" type="checkbox"/> Metallic	Number of gears	
Weight (kg)(kg):		Displacement(cc):	2199
Empty weight(kg):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Diesel
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	
Average consumption (l/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (g/km):	262
Cargo space (l):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	
Loading space length (cm):		Towing Capacity (kg):	
Loading space width (cm):		Load capacity (kg):	
Loading space height (cm):		Trailer Weight (kg):	
Hydraulic Installation:			

opties

<input checked="" type="checkbox"/> Alloy wheels	<input checked="" type="checkbox"/> Exterior mirrors with step light	<input checked="" type="checkbox"/> Climate control
<input checked="" type="checkbox"/> Leather upholstery	<input checked="" type="checkbox"/> Rear view camera	<input checked="" type="checkbox"/> Climate control (analog)
<input checked="" type="checkbox"/> Daytime running lights	<input checked="" type="checkbox"/> Rear parking sensors	<input checked="" type="checkbox"/> Climate control (digital)
<input checked="" type="checkbox"/> Towing hook	<input checked="" type="checkbox"/> Front parking sensors	<input checked="" type="checkbox"/> Climate control (L/R separated)
<input checked="" type="checkbox"/> Anti-lock braking system	<input checked="" type="checkbox"/> Towbar with fixed ball	<input checked="" type="checkbox"/> Large screen navigation
<input checked="" type="checkbox"/> ABS	<input checked="" type="checkbox"/> Rear-seat folding (equal parts)	<input checked="" type="checkbox"/> Keyless entry
<input checked="" type="checkbox"/> Airbag(s)	<input checked="" type="checkbox"/> Rear-seat folding (unequal parts)	<input checked="" type="checkbox"/> Keyless entry/start/stop
<input checked="" type="checkbox"/> Audio	<input checked="" type="checkbox"/> Tailgate	<input checked="" type="checkbox"/> Keyless start/stop
<input checked="" type="checkbox"/> Central locking system	<input checked="" type="checkbox"/> Sidebars	<input checked="" type="checkbox"/> Electrically operated rear windows
<input checked="" type="checkbox"/> Place to lie down	<input checked="" type="checkbox"/> Full partition with window	<input checked="" type="checkbox"/> Electrically operated front windows
<input checked="" type="checkbox"/> Fog lamps	<input checked="" type="checkbox"/> Aux connection	<input checked="" type="checkbox"/> Electrically folding mirrors
<input checked="" type="checkbox"/> Start/stop system	<input checked="" type="checkbox"/> iPod connection	<input checked="" type="checkbox"/> Electrically adjustable mirrors
<input checked="" type="checkbox"/> Stoelverwarming-Koeling	<input checked="" type="checkbox"/> USB connection	<input checked="" type="checkbox"/> Electrically heated driver's seat
<input checked="" type="checkbox"/> Power steering	<input checked="" type="checkbox"/> Bluetooth streaming	<input checked="" type="checkbox"/> Electrically heated passenger seat
<input checked="" type="checkbox"/> Front seats adjustable in height	<input checked="" type="checkbox"/> DAB+	<input checked="" type="checkbox"/> Central armrest front
<input checked="" type="checkbox"/> Multifunctional steering wheel	<input checked="" type="checkbox"/> Bluetooth car kit	<input checked="" type="checkbox"/> Ventilation driver's seat
<input checked="" type="checkbox"/> Remote central locking	<input checked="" type="checkbox"/> Radio	<input checked="" type="checkbox"/> Ventilation passenger seat
<input checked="" type="checkbox"/> Roof rail (black)	<input checked="" type="checkbox"/> Cruise control	<input checked="" type="checkbox"/> Audio control on the steering wheel
<input checked="" type="checkbox"/> Metallic finish	<input checked="" type="checkbox"/> Black top interior	<input checked="" type="checkbox"/> Leather steering wheel
<input checked="" type="checkbox"/> Halogen headlights	<input checked="" type="checkbox"/> Airconditioning	<input checked="" type="checkbox"/> Heated steering wheel
<input checked="" type="checkbox"/> Exterior mirrors in car body color	<input checked="" type="checkbox"/> Airconditioning in the back	

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	235/70 R17	Hankook	8
Tire left rear	Summer	Alloy	235/70 R17	nexen	4
Tire right front	Summer	Alloy	235/70 R17	Hankook	8
Tire right rear	Summer	Alloy	235/70 R17	nexen	4

Additional information

No. of keys: 2 ☐ Luxury key ☐ Instruction booklet ☐ Airco works

Interior color:	Black	Maintenance booklet:	<input checked="" type="checkbox"/> Odorless
Upholstery:	Leder		<input checked="" type="checkbox"/> Clean inside (Professional Cleaning)
No. of seats:	5	Stamp date:	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	<input checked="" type="checkbox"/> Vehicle special usage (Taxi)

 Cleaning

- ☒ Clean inside (Professional Cleaning)
- ☒ Clean outside (Cleaning)

 Damages

 Not acceptable



Front bumper - Scratch



Front bumper - Scratch



Front left screen - Scratch



Front left door - Scratch



Rear left door - Scratch



Left sill - Rust formation



Rear left screen - Scratch



Tailgate/ lid - Dent



Rear bumper - Break



Rear right screen - Dent



Rear right door - Dent



Front left door - Restyle dent



Windscreen - Pip



Aircopomp Defect



Bestuurderstoel beschadigd

🔧 Damages

⊕ Acceptable

⚙️ Extra options





